

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012054/KGA3Q2
Date: 05/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700065664
Claimant Vehicle No :	YQ2562X	Insured Vehicle No :	SLT2132S
Date of Loss:	03/11/2020	Nature of Claim:	TP
		Claim No:	7155523544SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ2562X	Engine No:	N04CWN10287
Make & Model:	HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M)	Chassis No:	JHHUCV3F70K034945
Reg. Date:	28/08/2020 (Man. Year: 2020)	Odometer:	9305 km
Colour:	White		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85 R16	Rear Tyre Size:	195/85 R16 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9/9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,613.74	6,206.04	407.70	6.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	2,150.00	580.00	21.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,343.74	8,356.04	987.70	10.57
+ GST 7.00/7.00% (S\$)	654.06	584.92	69.14	10.57

Nett Amount (S\$)	9,997.80	8,940.96	1,056.84	10.57
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		9,368.96		

INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 05/11/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Buckled	967.20 FL	*967.20 FL
2	1		*FRONT BUMPER LH BRACKET	Distorted	285.70 FL	*285.70 FL
3	1		*FRONT BUMPER LH FOG LAMP ASSY	Cracked	379.90 FL	*379.90 FL
4	1		*FRONT PANEL	Bent	598.70 FL	*598.70 FL
5	1		*FRONT LH STEP GARNISH	Repair	373.90 FL	*- FL
6	1		*FRONT PANEL -HINO	Necessary	35.90 FL	*35.90 FL
7	1		*FRONT PANEL -300	Necessary	37.50 FL	*37.50 FL
8	1		*FRONT GRILLE	Cracked	654.60 FL	*654.60 FL
9	1		*FRONT GRILLE LOGO	Necessary	71.30 FL	*71.30 FL
10	1		*SET FRONT GRILLE CLIPS	Necessary	36.00 FL	*36.00 FL
11	1		*HORN	Serviceable	79.10 FL	*- FL
12	1		*LH HEADLAMP	Cracked	1,014.60 FL	*1,014.60 FL
13	1		*RH HEADLAMP	Cracked	1,014.60 FL	*1,014.60 FL
14	1		*FRONT LH CORNAL GARNISH	Cracked	539.80 FL	*539.80 FL
15	1		*LH SIDE MIRROR STAY	Bent	275.70 FL	*275.70 FL
16	1		*LH SIDE MIRROR SQUARE	Missing	158.00 FL	*158.00 FL
17	1		*LH SIDE MIRROR ROUND	Missing	107.90 FL	*107.90 FL
18	1		*LH SIDE MIRROR CAP	Missing	13.10 FL	*13.10 FL
19	1		*LH DOOR GLASS	Cut	599.40 FL	*599.40 FL
20	1		*FRONT LH DOOR STICKER -616	Necessary	35.90 FL	*35.90 FL
21	1		*FRONT LH DOOR STICKER -EURO	Necessary	49.80 FL	*49.80 FL
22	1		*FRONT NUMBER PLATE	Bent	18.00 FS	*18.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,346.60	6,893.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	732.86	687.56
Total Parts (\$\$)	6,613.74	6,206.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,HEADLAMPS FRT LH CORNAL GARNISH ,STEP GARNISH ,KNOCK & REPAIR FRT LH WSCREEN PILLAR ,FRT INNER PANEL ,FRT CHASSIS MEMBER & REALIGN THE SAME	New	1,300.00	900.00
2	REMOVE & REFIX FRT LH DOOR GLASS & CHECK POWER MIRROR & CENTRE LOCKING	New	80.00	0.00
3	PUTTY & RESPRAY ON FRT BUMPER ,GRILLE ,FRT PANEL ,INNER PANEL ,FRT LH DOOR ,CORNAL PANEL	New	1,000.00	900.00
4	REMOVE & REFIX DASHBOARD ,METER ASSY & CHECK WIRING	New	250.00	250.00
5	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
Gross Labour Cost (\$)			2,730.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >