

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20012057/EPA3Q2

**Date:** 18/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070065286

**Claimant**  
**Vehicle No :** SHD4059P **Insured Vehicle No :** SMT2906P

Date of Loss: 04/11/2020 Nature of Claim: TP Claim No: 0881222023SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD4059P</b>	Engine No:	G4LEKU400872
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU187731
Reg. Date:	30/10/2019 (Man. Year: 2019)	Odometer:	118684 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,467.74	411.00	1,056.74	72.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	550.00	500.00	47.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,517.74</b>	<b>961.00</b>	<b>1,556.74</b>	<b>61.83</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	176.24	67.27	108.97	61.83
<b>Nett Amount (\$\$)</b>	<b>2,693.98</b>	<b>1,028.27</b>	<b>1,665.71</b>	<b>61.83</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (\$\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$125.19/day) (\$\$)</b>		250.38		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,380.65</b>		

### INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 04/11/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	* - FL
2	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	111.60 FL	* - FL
3	1		*REAR REINFORCEMENT	Not Necessary	294.80 FL	* - FL
4	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	* - FL
5	1		*REAR BUMPER CENTRE MOULDING	Cut	451.25 FL	*451.25 FL
6	1		*FOG LAMP	Not Necessary	201.00 FL	* - FL
7	1		*REVERSE SENSOR	Not Necessary	135.70 FS	* - FS
8	1		*BUMPER MAT	Not Necessary	50.00 FS	* - FS
9	1		*REAR NUMBER PLATE W/HOLDER	Broken	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,775.75</b>	<b>501.25</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	308.01	90.25
<b>Total Parts (\$)</b>	<b>1,467.74</b>	<b>411.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	640.00	320.00
2	SPRAY PAINTING CHARGE	New	300.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	0.00
4	CHECK LIGHTING	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,050.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >