

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012070/UPS3Q2

Date: 18/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMU926P	Insured Vehicle No :	SHC1574T
Date of Loss: 03/11/2020	Nature of Claim: TP	Claim No: MCT20110039

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU926P		
Make & Model:	TOYOTA PREVIA, 2.4 7-seater (A)	Engine No:	2AZ1B14576
Reg. Date:	07/08/2020 (Man. Year: 2019)	Chassis No:	JTEGD56M907173884
Colour:	Black	Odometer:	4364 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,855.50	7,306.70	4,548.80	38.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,610.76	8,752.76	1,858.00	17.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,466.26	16,059.46	6,406.80	28.52
+ GST 7.00/7.00% (S\$)	1,572.64	1,124.16	448.48	28.52
Nett Amount (S\$)	24,038.90	17,183.62	6,855.28	28.52
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
		18,083.62		

INSPECTION

Date of Assignment:	04/11/2020	
Date Inspected:	05/11/2020	Inspected At:
		Borneo Motors (S) Pte Ltd (Ubi)
		17 Ubi Road 4
		Singapore 408611
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2021)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU926P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*PANEL SUB-ASSY ,FR	Badly Dented	1,718.70 FS	*1,718.70 FS
3	1		*TAPE ,BLACK OUT FR	Necessary	43.80 FS	*43.80 FS
4	1		*TAPE ,BLACK OUT FR	Necessary	35.00 FS	*35.00 FS
5	1		*TAPE ,BLACK OUT FR	Necessary	52.30 FS	*52.30 FS
6	1		*TAPE ,BLACK OUT FR	Necessary	22.10 FS	*22.10 FS
7	1		*WEATHERSTRIP,FR	Not Necessary	205.20 FS	*- FS
8	1		*HINGE ASSY ,FR DOOR	Not Necessary	97.50 FS	*- FS
9	1		*HINGE ASSY ,FR DOOR	Not Necessary	110.60 FS	*- FS
10	1		*PANEL SUB-ASSY ,RR	Badly Dented	1,741.90 FS	*1,741.90 FS
11	1		*R/H SLIDE BLACK TAPE	Necessary	43.80 FS	*43.80 FS
12	1		*R/H SLIDE BLACK TAPE	Necessary	48.20 FS	*48.20 FS
13	1		*R/H SLIDE BLACK TAPE	Necessary	26.40 FS	*26.40 FS
14	1		*R/H SLIDE BLACK TAPE	Necessary	35.00 FS	*35.00 FS
15	1		*R/H SLIDE BLACK TAPE	Necessary	30.70 FS	*30.70 FS
16	1		*SENSOR ASSY ,POWER	Torn / Damaged	1,285.20 FS	*1,285.20 FS
17	1		*PANEL ,ROCKER OUTER	Repair	317.20 FS	*- FS
18	1		*PANEL SUB-ASSY	Repair	990.00 FS	*- FS
19	1		*COVER RR BUMPER	Repair	596.90 FS	*- FS
20	10		*CLIPS	Not Necessary	41.00 FS	*- FS
21	1		*WHEEL ,DISC	Repair	2,190.40 FS	*- FS
22	1		*REAR MUDGUARD SUB-ASSY	Missing	1,367.40 FS	*1,367.40 FS
23	1		*FRONT MUDGUARD SUB-ASSY	Missing	818.10 FS	*818.10 FS
24	1		*BRACKET ,SIDE	Necessary	8.10 FS	*8.10 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **11,855.50** **7,306.70**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE RH REAR TYRE (80%)	New	580.00	464.00
2	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON RH ACCIDENT AREAS	New	366.36	366.36
3	REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING	New	72.00	0.00
4	SUPPLY SELANAT (NETT)-RH BOTH DOOR	New	120.00	120.00
5	CHECK LIGHTING & WIRING SYSTEM	New	122.40	122.40
6	TRANSFER & INSTALL COMPONENTS TO NEW DOOR	New	720.00	720.00
7	REMOVE & INSTALL CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR	New	360.00	360.00
8	REMOVE & INSTALL REAR REVERSE SENSOR	New	180.00	180.00
9	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
10	REPLACE RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH ACCIDENT AFFECTED AREAS	New	3,600.00	2,520.00
11	RESPRAY JOB ON RH ACCIDENT AFFECTED AREA	New	4,130.00	3,540.00
12	CONDUCT FULL WHEEL ALIGNMENT	New	180.00	180.00
Gross Labour Cost (\$\$)			10,610.76	8,752.76

Report was unsubmitted during this print-out.

< END OF ESTIMATES >