

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012071/KVF3E2

Date: 14/12/2020

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 0999993863
Date of Loss: 31/10/2020 Nature of Claim: OD Claim No: 2404437540SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW8028E**
Make & Model: MERCEDES-BENZ GLA180, 1.6 (A) Engine No: 27091031549973
Reg. Date: 01/03/2018 (Man. Year: 2017) Chassis No: WDC1569422J478549
Colour: Metallic Grey Odometer: 34363 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$101,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Continental 7 mm Rear Left Side: Continental 8 mm
Front Right Side: Continental 7 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,671.55	4,661.60	9.95	0.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	630.00	1,410.00	69.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,711.55	5,291.60	1,419.95	21.16
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	5,511.55	4,091.60	1,419.95	25.76
+ GST 7.00/7.00% (S\$)	385.81	286.41	99.40	25.76
Nett Amount (S\$)	5,897.36	4,378.01	1,519.35	25.76

INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 05/11/2020 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Bent	850.00 F	*850.00 F
2	1		*FRONT BUMPER BASIC MOUNTING (WCP)	Serviceable	155.00 F	*- F
3	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	280.00 F	*280.00 F
4	1		*FRONT BUMPER SPONGE (WCP)	Cracked	115.00 F	*115.00 F
5	1		*FRONT BUMPER CENTRE EMBLEM (WCP)	Necessary	58.00 F	*58.00 F
6	1		*FRONT BUMPER LOWER CHROME (WCP)	Cracked	580.00 F	*580.00 F
7	1		*FRONT BUMPER LOWER CENTRE GRILLE (WCP)	Dented	125.00 F	*125.00 F
8	1		*FRONT BUMPER LOWER GARNISH-LH (WCP)	Cut	115.00 F	*115.00 F
9	1		*FRONT BUMPER SENSOR (WCP)	Shorted	138.00 F	*138.00 F
10	6		*FRONT BUMPER SENSOR SEALS (WCP)	Necessary	48.00 F	*48.00 F
11	1		*FRONT BUMPER CLIPS (WCP) (15PCS)	Necessary	107.25 FS	*50.00 FS
12	1		*FRONT GRILLE (WCP)	Cracked	250.00 F	*250.00 F
13	2		*FRONT GRILLE LOWER BEAM (WCP)	Cracked	198.00 F	*396.00 F
14	1		*FRONT GRILLE CENTRE LOGO (WCP)	Cracked	102.00 F	*102.00 F
15	1		*FRONT GRILLE CENTRE LOGO BASE (WCP)	Cracked	68.00 F	*68.00 F
16	1		*FRONT GRILLE CENTRE LOGO OUTER GARNISH (WCP)	Cracked	82.00 F	*82.00 F
17	1		*FRONT NUMBER PLATE GARNISH (WCP)	Bent	98.00 F	*98.00 F
18	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
19	1		*FRONT BUMPER UNDER COVER (WCP)	Cracked	225.00 F	*225.00 F
20	1		*INTER-COOLER ASSY (WCP)	Puncture	558.00 F	*558.00 F
21	1		*AIR DUCT (WCP)	Cracked	68.00 F	*68.00 F
					<hr/>	
					Sub Total (\$\$)	4,260.25 4,246.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	411.30 415.60
					<hr/>	
					Total Parts (\$\$)	4,671.55 4,661.60
					<hr/>	

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR AND CHECK WIRING SYSTEM	New	120.00	60.00
2	TO PANEL BEAT AND STRAIGHTEN,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	1,000.00	300.00
3	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	800.00	220.00
4	TO REMOVE AND REFIT INTER-COOLER ASSY	New	120.00	50.00
Gross Labour Cost (\$\$)			2,040.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >