

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20012081/EPS3Q2**Date:** 07/12/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015		
<b>Claimant</b>				
<b>Vehicle No :</b> SBS6536H	<b>Insured Vehicle No :</b>	SH6592B		
Date of Loss: 30/10/2020	Nature of Claim:	TP	Claim No:	MCT20100496

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBS6536H</b>			
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A)	Engine No:	902926C1074169	
Reg. Date:	02/03/2015 (Man. Year: 2014)	Chassis No:	WEB62808323126623	
Colour:	Green	Odometer:	361262 km	
Engine Capacity:	6374 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/60R22.5	Rear Tyre Size:	295/60R22.5(D)
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5/5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5/5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,707.05	8,177.39	5,529.66	40.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,360.00	2,050.00	5,310.00	72.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>21,067.05</b>	<b>10,227.39</b>	<b>10,839.66</b>	<b>51.45</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,474.69</b>	<b>715.92</b>	<b>758.77</b>	<b>51.45</b>
<b>Nett Amount (S\$)</b>	<b>22,541.74</b>	<b>10,943.31</b>	<b>11,598.43</b>	<b>51.45</b>
<b>+ Loss of Use (4.0 x S\$250.00/day) (S\$)</b>		1,000.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>11,950.76</b>		

INSPECTION

Date of Assignment:	04/11/2020	
Date Inspected:	09/11/2020 Inspected At:	LexBuild International Pte Ltd (HQ) 11 Tuas Bay Close, #04-02 West Star Singapore 636996
Estimated Period of Repair:	4.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 25 Nov 2020)	
<b>Parts:</b>	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBS6536H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHS 2ND BODYPANEL	Dented	4,725.27 F	*4,725.27 FL
2	1		*DOOR NUMBER 4 RUBBER (C TYPE)	Cut	793.78 F	*793.78 FL
3	1		*EXIT DOOR FRAME ASSEMBLY (MOULDING)	Cut	3,216.54 F	*3,216.54 FL
4	1		*DOOR GLASS NUMBER 3	Not Necessary	2,290.53 F	*- FL
5	1		*DOOR GLASS NUMBER 4	Not Necessary	2,290.53 F	*- FL
6	2		*MARKET LAMP	Cut	290.40 F	*290.40 FL
7	1		*SG <3 BUS STICKER	Necessary	50.00 F	*30.00 FL
8	1		*GO-AHEAD SIGNAPORE STICKER	Necessary	50.00 F	*30.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>13,707.05</b>	<b>9,085.99</b>
<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	0.00	908.60
<b>Total Parts (S\$)</b>	<b>13,707.05</b>	<b>8,177.39</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SUPPLY SKILLED LABOUR TO REPLACE:LHS 2ND BODYPANEL,DOOR NUMBER 4 RUBBER (C TYPE), EXIT DOOR FRAME ASSEMBLY	New	2,200.00	1,000.00
2	SUPPLY SKILLED LABOUR & SIKA265/PRIMER/ACTIVATOR TO REPLACE EXIT DOOR NUMBER 3 & DOOR NUMBER 4	New	1,760.00	0.00
3	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO PUTTY GRINDING & SPRAYPAINT: LHS 2ND BODYPANEL (2 PC),LHS REAR WHEELARC PANEL (1PC),LHS REAR LOWER SKIRTING (1PC)	New	3,200.00	1,000.00
4	SUPPLY ELECTRICIAN TO REPLACE 2 MARKER LAMP	New	200.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,360.00</b>	<b>2,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >