

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012086/APA3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLE2979U	Insured Vehicle No :	SHC2533E
Date of Loss: 02/11/2020	Nature of Claim: TP	Claim No: MCT20110013

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE2979U		
Make & Model:	HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	L15B4035114
Reg. Date:	15/07/2016 (Man. Year: 2016)	Chassis No:	RU11115107
Colour:	White	Odometer:	81723 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,407.92	4,109.84	9,298.08	69.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,720.00	1,980.00	53.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,107.92	5,829.84	11,278.08	65.92
Approved Total (Overridden) (\$\$)		4,600.00		
Nett Amount (\$\$)	17,107.92	4,600.00	12,507.92	73.11
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	04/11/2020	
Date Inspected:	05/11/2020 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2021)
Parts:	144	HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE2979U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	506.00 FL	*- FL
2	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	34.00 FL	*- FL
3	1		*FRONT BUMPER LOWER LIP	Cut	215.20 FL	*215.20 FL
4	1		*FRONT LH FENDER	Repair	434.50 FL	*- FL
5	1		*FRONT LH FENDER SIDE GARNISH	Cut	198.00 FL	*198.00 FL
6	2		*FRONT LH DOOR	Dented	927.10 FL	*927.10 FL
7	1		*FRONT LH DOOR GLASS OUTER MOULDING	Not Necessary	66.00 FL	*- FL
8	1		*FRONT LH DOOR SUN VISOR	Necessary	88.00 FS	*60.00 FS
9	1		*SET FRONT LH DOOR FRAME BLACK STICKER	Necessary	28.90 FL	*28.90 FL
10	1		*FRONT LH DOOR SIDE MIRROR ASSY	Damaged	803.00 FL	*803.00 FL
11	1		*FRONT LH SHOCK ABSORBER	Bent	473.20 FL	*473.20 FL
12	1		*FRONT LH KNUCKLE ARM	Damaged	274.70 FL	*274.70 FL
13	2		*FRONT LH KNUCKLE ARM BEARING	Necessary	149.10 FL	*149.10 FL
14	1		*FRONT LH LOWER ARM	Bent	385.00 FL	*385.00 FL
15	1		*FRONT LH LINKAGE	Not Necessary	66.00 FL	*- FL
16	2		*FRONT LH DRIVE SHAFT	Not Necessary	1,210.00 FL	*- FL
17	2		*STEERING RACK	Not Necessary	1,289.70 FL	*- FL
18	2		*LH ROCKER PANEL GARNISH	Cut	415.30 FL	*415.30 FL
19	1		*REAR LH DOOR	Repair	968.10 FL	*- FL
20	1		*REAR LH DOOR GLASS OUTER MOULDING	Not Necessary	71.50 FL	*- FL
21	1		*SET REAR LH DOOR FRAME BLACK STICKER	Not Necessary	30.50 FL	*- FL
22	2		*REAR LH DOOR SUN RISE	Not Necessary	110.00 FL	*- FL
23	1		*REAR LH DOOR SIDE RUBBER	Not Necessary	44.50 FL	*- FL
24	1		*REAR LH FENDER	Repair	602.40 FL	*- FL
25	1		*REAR LH FENDER SIDE GARNISH	Cut	310.00 FL	*192.80 FL
26	1		*REAR LH SHOCK ABSORBER	Not Necessary	363.00 FL	*- FL
27	1		*REAR LH KNUCKLE ARM	Not Necessary	1,664.50 FL	*- FL
28	2		*REAR LH KNUCKLE ARM BEARING	Not Necessary	345.40 FL	*- FL
29	1		*REAR AXLE	Not Necessary	1,664.30 FL	*- FL
30	1		*FRONT LH TYRE	Not Necessary	350.00 FS	*- FS
31	1		*FRONT LH SPORT RIM	Cut	850.00 FS	*400.00 FS
32	1		*REAR LH TYRE	Not Necessary	350.00 FS	*- FS
33	1		*REAR LH SPORT RIM	Cut	850.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,137.90	4,922.30
- List Item Discount on L Items 20.00/20.00% (\$)	2,729.98	812.46
Total Parts (\$)	13,407.92	4,109.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	REMOVE & REINSTALL DOOR FITTINGS	New	150.00	80.00
3	REMOVE & REINSTALL FRONT AND REAR SUSPENSION	New	600.00	220.00
4	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,400.00	500.00
5	RESPRAY PAINTING	New	1,300.00	800.00
6	TUFF KOTE	New	150.00	40.00
Gross Labour Cost (\$\$)			3,700.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >