

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012087/EGA3Q2

Date: 15/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993937

Claimant
Vehicle No : SHC2202K **Insured Vehicle No :** GBF458H

Date of Loss: 04/11/2020 Nature of Claim: TP Claim No: 0967807314SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2202K	Engine No:	G4LEKU397944
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU186813
Reg. Date:	22/10/2019 (Man. Year: 2019)	Odometer:	85487 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,937.48	510.00	1,427.48	73.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	550.00	680.00	55.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,167.48	1,060.00	2,107.48	66.53
+ GST 7.00/7.00% (\$\$)	221.72	74.20	147.52	66.53
Nett Amount (\$\$)	3,389.20	1,134.20	2,255.00	66.53
+ Loss of Use (1.5 x S\$50.00/day) (\$\$)		75.00		
+ Car Rental (1.5 x S\$125.19/day) (\$\$)		187.79		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		1,404.48		

INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 04/11/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	2		*REAR BUMPER SIDE BRACKET RH/LH	Not Necessary	111.60 FL	*- FL
3	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
5	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	276.20 FL	*- FL
6	1		*REAR BUMPER LOWER MOULDING	Cut	155.00 FL	*155.00 FL
7	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
8	1		*REAR BUMPER CENTRE MOULDING	Cut	451.25 FL	*451.25 FL
9	2		*REAR BUMPER REFLECTOR RH/LH	Not Necessary	63.80 FL	*- FL
10	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	*- FL
11	1		*REAR NUMBER PLATE /W HOLDER	Broken	50.00 FS	*25.00 FS
12	1		*REAR REVERSE SENSOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,364.35	631.25
- List Item Discount on L Items 20.00/20.00% (S\$)	426.87	121.25
Total Parts (S\$)	1,937.48	510.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	650.00	320.00
2	SPRAY PAINTING CHARGE	New	400.00	200.00
3	CHECK WIRING	New	60.00	30.00
4	TUFF KOTE	New	60.00	0.00
5	REMOVE /REFIX REVERSE SENSOR	New	60.00	0.00
Gross Labour Cost (\$\$)			1,230.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >