

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG20012088/AGQF3Q2**Date:** 16/11/2020REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29140510ALM
<b>Claimant</b>		
<b>Vehicle No :</b> SMS4936U	<b>Insured Vehicle No :</b>	SFS3612T
Date of Loss: 03/11/2020	Nature of Claim:	TP
		Claim No: 630580

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMS4936U</b>		
Make & Model:	MERCEDES-BENZ C180 BLUE EFFICIENCY, 1.6 (A)	Engine No:	27491030042145
Reg. Date:	10/05/2013 (Man. Year: 2013)	Chassis No:	WDD2040312A840522
Colour:	Red	Odometer:	128986 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	8,480.00	3,710.70	4,769.30	56.24	
Miscellaneous Items	0.00	0.00	0.00		
Labour	3,850.00	1,290.00	2,560.00	66.49	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>12,330.00</b>	<b>5,000.70</b>	<b>7,329.30</b>	<b>59.44</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>			
	(S\$)	12,330.00	4,000.00	8,330.00	67.56
<b>+ GST 7.00/7.00% (S\$)</b>	863.10	280.00	583.10	67.56	
<b>Nett Amount (S\$)</b>	<b>13,193.10</b>	<b>4,280.00</b>	<b>8,913.10</b>	<b>67.56</b>	

INSPECTION

Date of Assignment:	06/11/2020		
Date Inspected:	05/11/2020	Inspected At:	Stk Auto (s) Pte Ltd (HQ) 8 kaki bukit ave4, #03-21 Singapore 415875
Estimated Period of Repair:	5.0 days		

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2020)
<b>Parts:</b> 143	MERCEDES-BENZ C180 BLUE EFFICIENCY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMS4936U)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,700.00 FL	*- FL
2	1		*BOOT LID EMBLEM C180	Necessary	95.00 FL	*95.00 FL
3	1		*BOOT LID EMBLEM 7G-TRONIC	Necessary	95.00 FL	*95.00 FL
4	1		*BOOT LID C&C	Necessary	95.00 FL	*95.00 FL
5	1		*BOOT LID CHROME	Not Necessary	450.00 FL	*- FL
6	1		*BOOT LID LOCK	Not Necessary	350.00 FL	*- FL
7	1		*RH TAILLAMP	Not Necessary	690.00 FL	*- FL
8	1		*LH TAILLAMP	Not Necessary	690.00 FL	*- FL
9	1		*REAR BUMPER	Deformed	1,605.00 FL	*1,442.00 FL
10	1		*REAR BUMPER LOWER GARNISH	Not Necessary	65.00 FL	*- FL
11	1		*REAR BUMPER RETAINER RH	Necessary	65.00 FL	*65.00 FL
12	1		*REAR BUMPER RETAINER LH	Necessary	450.00 FL	*65.00 FL
13	1		*REAR BUMPER SENSOR	Damaged	250.00 FL	*250.00 FL
14	1		*REAR BUMPER LOWER	Deformed	195.00 FL	*195.00 FL
15	1		*REAR END PANEL	Dented	1,560.00 FL	*1,206.00 FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	215.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	720.00 FL	*615.00 FL
19	1		*REAR NUMBER PLATE	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,415.00</b>	<b>4,123.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	935.00	412.30
<b>Total Parts (\$)</b>	<b>8,480.00</b>	<b>3,710.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,500.00	600.00
2	TO SPRAY PAINT ON ACCIDENT AREAS	New	1,500.00	600.00
3	TO REMOVE AND REFIT BOOT LID COMPARTMENT	New	200.00	0.00
4	TO CHECK WIRING AND TAILLAMP	New	150.00	30.00
5	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
6	TO RUST PROOFING ACCIDENT AREAS	New	150.00	60.00
7	TO COMPUTER DIAGNOSTIC TEST	New	250.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,290.00</b>
			<b>3,850.00</b>	<b>1,290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >