

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012091/R1TF3E2

Date: 30/04/2021

REFERENCE

Insured/Claimant:	LAI XIANGRU, HELENE	Policy No:	1900000731		
Date of Loss:	04/11/2020	Nature of Claim:	OD	Claim No:	4503822221SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGA61K		
Make & Model:	CITROEN C4 CACTUS, 1.2 AT6 (A)	Engine No:	10XVA10925695
Reg. Date:	23/01/2019 (Man. Year: 2018)	Chassis No:	VF70PHNZWJE503294
Colour:	Yellow	Odometer:	14323 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,684.40	14,472.40	1,212.00	7.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,425.00	11,735.00	4,690.00	28.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,109.40	26,207.40	5,902.00	18.38
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	31,509.40	25,607.40	5,902.00	18.73
+ GST 7.00/7.00% (S\$)	2,205.66	1,792.52	413.14	18.73
Nett Amount (S\$)	33,715.06	27,399.92	6,315.14	18.73

INSPECTION

Date of Assignment: 05/11/2020

Date Inspected: 05/11/2020 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 20.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LOAD FLOOR ASSY	Buckled	796.00 FL	*796.00 FL
2	1		*TAILGATE PROP (2X) (NPA)	Serviceable	0.00 FL	*- FL
3	1		*REAR WING RH	Buckled	1,323.00 FL	*1,323.00 FL
4	1		*REAR LIGHT HOUSING LH (NPA)	Serviceable	0.00 FL	*- FL
5	1		*REAR LIGHT HOUSING RH (NPA)	Serviceable	0.00 FL	*- FL
6	1		*RR QTR DECORATION LH	Necessary	30.00 FL	*- FL
7	1		*RR QTR DECORATION RH	Necessary	23.00 FL	*- FL
8	1		*RR QTR DECORATION LH INF	Necessary	15.00 FL	*15.00 FL
9	1		*RR QTR DECORATION RH INF	Necessary	15.00 FL	*15.00 FL
10	1		*TAIL-LIGHT LH	Broken	275.00 FL	*275.00 FL
11	1		*EXHAUST INTERMEDIATE PIPE	Bent	828.00 FL	*828.00 FL
12	1		*EXHAUST SYSTEM HEATSHIELD	Bent	79.00 FL	*79.00 FL
13	1		*TRUNK MAT	Cracked	298.00 FL	*298.00 FL
14	1		*BOOT SIDE TRIM LH	Deformed	119.00 FL	*119.00 FL
15	1		*BOOT SIDE TRIM RH	Deformed	119.00 FL	*119.00 FL
16	1		*PIROTECHNIC SAFETY BELT LH	Activated	742.00 FL	*742.00 FL
17	1		*PIROTECHNIC SAFETY BELT RH	Activated	742.00 FL	*742.00 FL
18	1		*SAFETY BELT BUCKLE LH	Necessary	200.00 FL	*200.00 FL
19	1		*SAFETY BELT BUCKLE RH	Necessary	200.00 FL	*200.00 FL
20	1		*RR WINDOW WIPER MOTOR (NPA)	Serviceable	0.00 FL	*- FL
21	1		*FRT SEAT SQUAB FRAME RH (NPA)	Serviceable	0.00 FL	*- FL
22	1		*FRT SEATBACK FRAME RH	Bent	681.00 FL	*681.00 FL
23	1		*FRT SEAT CUSHION PADDING RH (NPA)	Serviceable	0.00 FL	*- FL
24	1		*FRT SEAT SQUAD PADDING RH	Serviceable	0.00 FL	*- FL
25	1		*RR NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
26	1		*REAR BUMPER	Deformed	944.00 FL	*944.00 FL
27	1		*BUMPER SKIRT	Cracked	446.00 FL	*446.00 FL
28	1		*BMPR RUBBR BOOT RH	Deformed	166.00 FL	*166.00 FL
29	1		*RECESS DOOR	Not Necessary	78.00 FL	*- FL
30	1		*SET BRACKET	Necessary	104.00 FL	*104.00 FL
31	1		*SET BRACKET	Necessary	133.00 FL	*133.00 FL
32	1		*BUMPER BRACKET	Necessary	83.00 FL	*83.00 FL
33	1		*BUMPER ABSORBER AR	Bent	280.00 FL	*280.00 FL
34	1		*LOW RR PAN FIX	Necessary	106.00 FL	*106.00 FL
35	1		*REAR PANEL ASSY	Bent	551.00 FL	*551.00 FL
36	1		*REAR PANEL OUTER	Bent	441.00 FL	*441.00 FL
37	1		*TAILGATE ASSY	Bent	1,248.00 FL	*1,248.00 FL
38	2		*TAILGATE HINGE	Bent	200.00 FL	*200.00 FL
39	1		*TAILGATE GLASS	Not Necessary	317.00 FL	*- FL
40	12		*GLASS WEDGE	Necessary	12.00 FL	*12.00 FL
41	1		*WEATHERSTRIP	Serviceable	169.00 FL	*- FL
42	1		*TAILGATE CAPPING	Deformed	534.00 FL	*534.00 FL
43	1		*SEAL WASHER	Necessary	47.00 FL	*47.00 FL
44	1		*MLDG FIXING REINF	Not Necessary	125.00 FL	*- FL
45	1		*LOWER TRIM	Serviceable	385.00 FL	*- FL
46	1		*TAILGATE FIX	Necessary	221.00 FL	*221.00 FL
47	1		*BADGE-LOGO	Necessary	72.00 FL	*72.00 FL
48	1		*BADGE-CACTUS	Necessary	72.00 FL	*72.00 FL
49	1		*REAR WING LH COUPE	Bent	1,272.00 FL	*1,272.00 FL
50	1		*RAIN GUTTER LH ASSY	Necessary	267.00 FL	*267.00 FL
51	1		*RAIN GUTTER RH ASSY	Necessary	267.00 FL	*267.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*MUDGUARD LH	Serviceable	114.00 FL	*- FL
53	1		*MUDGUARD RH	Serviceable	130.00 FL	*- FL
54	1		*WING MOULDING LH	Cracked	132.00 FL	*132.00 FL
55	1		*WING MOULDING RH	Cracked	154.00 FL	*154.00 FL
56	2		*LICEN PLAT LAMP	Cracked	54.00 FL	*54.00 FL
57	1		*TAIL-LIGHT RH	Broken	275.00 FL	*275.00 FL
58	4		*SENSOR	Distorted	756.00 FL	*756.00 FL
59	1		*REAR SILENCER PSA 4385	Bent	663.00 FL	*663.00 FL
60	1		*SILL TRIM	Cracked	91.00 FL	*91.00 FL
61	1		*TAILGATE LOCK	Distorted	104.00 FL	*104.00 FL
62	1		*HANDLE	Deformed	36.00 FL	*36.00 FL
63	1		*BOOT STRIKER	Serviceable	55.00 FL	*- FL
64	1		*BLADE-HOLDER	Serviceable	54.00 FL	*- FL
65	1		*WIPER BLADE L 240	Serviceable	23.00 FL	*- FL
66	1		*MOTOR SPACER	Not Necessary	12.00 FL	*- FL
67	1		*DECORATION LH SUPERIEUR (Supplementary)	Necessary	30.00 FL	*30.00 FL
68	1		*DECORATION RH SUPERIEUR (Supplementary)	Necessary	23.00 FL	*23.00 FL
69	1		*WHEEL FIX PLATE (Supplementary)	Distorted	15.00 FL	*15.00 FL
70	1		*SIDEMEMBER LH (Supplementary)	Bent	144.00 FL	*144.00 FL
71	1		*FIX STIFFENER LH AR (Supplementary)	Deformed	75.00 FL	*75.00 FL
72	1		*AIR PULLER (Supplementary)	Cracked	47.00 FL	*47.00 FL
73	1		*SOUND PROOFING LH SUPPORT (Supplementary)	Cracked	194.00 FL	*194.00 FL
74	1		*SOUND PROOFING RH SUPPORT (Supplementary)	Cracked	194.00 FL	*194.00 FL
75	1		*REINFORCEMENT (Supplementary)	Cracked	125.00 FL	*125.00 FL
76	1		*SUPPORT SCREW KIT (Supplementary)	Necessary	31.00 FL	*31.00 FL
77	1		*BOX CDE S/G (Supplementary)	Shorted	426.00 FL	*426.00 FL
78	1		*FRONT PIPE SLEEVE DIAM 42 (Supplementary)	Necessary	113.00 FL	*113.00 FL
79	1		*BUMPER HARNESS (Supplementary)	Cut	173.00 FL	*173.00 FL
80	1		*AIR PULLER (Supplementary)	Cracked	47.00 FL	*47.00 FL
81	1		*BMPR RUBBR BOOT LH	Deformed	156.00 FL	*156.00 FL
82	1		*BADGE - C4	Necessary	72.00 FL	*72.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,593.00	18,078.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,908.60	3,605.60
Total Parts (\$\$)	15,684.40	14,472.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER, RR END PNL, RR FLR PNL, TAILGATE, LHR FENDER & RHR FENDER - REPAIR LHR DOOR, RHR DOOR, ROOF PNL & RR CHASSIS LH / RH	New	7,500.00	5,000.00
2	RESPRAY RR BUMPER, TAILGATE, RR FLR PNL, RR END PNL, ROOF PNL, LHR FENDER, LHR WHEELHOUSE, RHR FENDER, RHR WHEELHOUSE & RR CHASSIS	New	4,180.00	3,150.00
3	RENEW RHF SEAT INCLUDED CUSHION AND SEAT FRAME	New	500.00	250.00
4	REMOVE & REFIT TAILGATE COMPONENT	New	120.00	120.00
5	REMOVE & REFIT FUEL TANK ASSY	New	500.00	250.00
6	RENEW RR EXHAUST MUFFLER ASSY	New	500.00	250.00
7	REMOVE & REFIT RR SEAT, TRIM, FLR BOARD & CARPET	New	120.00	120.00
8	REMOVE & REFIT ROOF LINING	New	250.00	250.00
9	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	225.00	225.00
11	CONDUCT CHASSIS ALIGNMENT - CELETTE BENCH	New	1,000.00	1,000.00
12	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	180.00	180.00
13	APPLY ANTI CORROSION ON AFFECTED AREAS	New	160.00	80.00
14	SUPPLY BODY PNL SEALANT	New	80.00	60.00
15	REMOVE & REFIT RR WINDSCREEN GLASS	New	300.00	300.00
16	INSTALL RR WINDSCREEN SOLAR FILM	New	280.00	0.00
17	SUPPLY WINDSCREEN SEALANT	New	80.00	80.00
18	RENEW REVERSE SENSOR	New	80.00	80.00
19	SUNDRIES	New	50.00	20.00
20	C&C BADGE	New	40.00	40.00
21	REPLACE SAFETY BELT, SRS CONTROL UNIT, & SEAT BUCKLE (Supplementary)	New	250.00	250.00
Gross Labour Cost (\$\$)			16,425.00	11,735.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >