

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012093/ASD3E2

Date: 14/04/2021

REFERENCE

Insured/Claimant: GERARD TAN YAU BOON(GERARD CHEN YAO WEN) Policy No: 1900155348
Date of Loss: 30/10/2020 Nature of Claim: OD Claim No: 3288732905SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN8785M**
Make & Model: AUDI A4, 2.0 TFSI Limited Edition (A) Engine No: CVK084102
Reg. Date: 30/08/2019 (Man. Year: 2019) Chassis No: WAUZZZF41KA086571
Colour: White Odometer: 11826 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$130,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,131.00	14,036.48	16,094.52	53.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,472.00	6,352.00	7,120.00	52.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,603.00	20,388.48	23,214.52	53.24
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	43,053.00	19,838.48	23,214.52	53.92
+ GST 7.00/7.00% (S\$)	3,013.71	1,388.69	1,625.02	53.92
Nett Amount (S\$)	46,066.71	21,227.17	24,839.54	53.92

INSPECTION

Date of Assignment: 05/11/2020
Date Inspected: 04/11/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,171.00 FS	*1,736.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	580.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Cracked	194.00 FS	*154.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Torn	208.00 FS	*166.00 FS
6	1		*RADIATOR GRILLE	Cracked	1,317.00 FS	*1,053.60 FS
7	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	268.00 FS	*- FS
8	1		*FRONT BUMPER CARRIER	Bent	795.00 FS	*635.60 FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
10	1		*FRONT BUMPER TOP COVER	Cracked	126.00 FS	*100.40 FS
11	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
12	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
13	1		*LOCK CARRIER BRACKET	Cracked	136.00 FS	*108.40 FS
14	2		*LOCK CARRIER BRACKET SUPPORT-LH/RH	Damaged	56.00 FS	*44.48 FS
15	1		*HORN-LH HIGH TONE	Not Necessary	124.00 FS	*- FS
16	1		*HORN-RH LOW TONE	Not Necessary	124.00 FS	*- FS
17	2		*SPRING SHACKLE-LH/RH	Not Necessary	58.00 FS	*- FS
18	2		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	484.00 FS	*- FS
19	1		*BONNET	Dented	2,763.00 FS	*2,210.40 FS
20	1		*BONNET ATTACHMENT PARTS	Not Necessary	408.00 FS	*- FS
21	2		*BONNET LID HINGE-LH/RH	Not Necessary	602.00 FS	*- FS
22	1		*BONNET IMPACT PROTECTION-CENTRE	Necessary	27.00 FS	*21.52 FS
23	1		*BONNET IMPACT PROTECTION-LH	Necessary	28.00 FS	*21.84 FS
24	1		*BONNET IMPACT PROTECTION-RH	Necessary	27.00 FS	*21.52 FS
25	2		*BONNET STRIKER-LH/RH	Not Necessary	100.00 FS	*- FS
26	2		*BONNET LID LOCK	Not Necessary	423.00 FS	*- FS
27	1		*BONNET LID CABLE-CENTRE	Damaged	57.00 FS	*45.52 FS
28	1		*BONNET RELEASE CABLE	Not Necessary	57.00 FS	*- FS
29	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
30	1		*LED HEADLIGHT-LH/RH	N/S Not Necessary / O/SCracked	15,386.00 FS	*6,154.40 FS
31	2		*LIFT CYLINDER-LH/RH	Not Necessary	416.00 FS	*- FS
32	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	92.00 FS	*- FS
33	1		*LOCK CARRIER	Cracked	1,004.00 FS	*803.20 FS
34	1		*AIRCON CONDENSER	Dented	615.00 FS	*492.00 FS
35	1		*TEMPERATURE SENSOR BRACKET	Cracked	18.00 FS	*14.40 FS
36	1		*READY MIX COOLANT	Necessary	177.00 FS	*141.44 FS
37	1		*RADIATOR AIR GUIDE-LH/RH OUTER	O/S Cracked	56.00 FS	*22.08 FS
38	1		*RADIATOR AIR GUIDE-LH/RH INNER	O/S Cracked	24.00 FS	*9.36 FS
39	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	16.00 FS	*- FS
40	2		*WINDOW SLOT SEAL-LH/RH	Not Necessary	606.00 FS	*- FS
41	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
42	1		*SUNDRIES	Necessary	300.00 FS	*18.72 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 30,131.00 14,036.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES	New	700.00	500.00
3	TO DISMANTLE AND REINSTALL BOTH FROTN DOOR PANEL TRIMS.TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY	New	700.00	280.00
4	TO REMOVE AND REINSTALL AIRCON CONDENSER,CHARGED AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTH HEADLIGHTS.TO REPAIR BOTH FRONT FENDERS.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PART REMOVED	New	4,900.00	2,250.00
6	TO RESPRAY FRONT BUMPER,BONNET,HINGES,BOTH FRONT FENDERS AND BOTH FRONT DOORS	New	5,500.00	1,650.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			13,472.00	6,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >