

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20012095/AVD3Q2

**Date:** 19/03/2021

### REFERENCE

Insured/Claimant:	TAN YUH HARN	Policy No:	2100456681-04	
Date of Loss:	30/10/2020	Nature of Claim:	OD	Claim No: 3342758492SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGY57Y</b>		
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR002365
Reg. Date:	30/03/2016 (Man. Year: 2015)	Chassis No:	WAUZZZ4M6GD028738
Colour:	Blue	Odometer:	86414 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	255/55R19	Rear Tyre Size:	255/55R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,837.00	4,301.20	4,535.80	51.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,382.00	2,752.00	2,630.00	48.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,219.00</b>	<b>7,053.20</b>	<b>7,165.80</b>	<b>50.40</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>13,219.00</b>	<b>6,053.20</b>	<b>7,165.80</b>	<b>54.21</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>925.33</b>	<b>423.72</b>	<b>501.61</b>	<b>54.21</b>
<b>Nett Amount (S\$)</b>	<b>14,144.33</b>	<b>6,476.92</b>	<b>7,667.41</b>	<b>54.21</b>

### INSPECTION

Date of Assignment:	05/11/2020	
Date Inspected:	04/11/2020	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TOP BUMPER	Deformed	1,215.00 FS	*972.00 FS
2	1		*REAR LOWER BUMPER	Deformed	1,815.00 FS	*1,452.00 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	205.00 FS	*- FS
4	1		*REAR LOWER SPOILER	Deformed	1,247.00 FS	*997.60 FS
5	1		*REAR LOWER SPOILER STRIP	Not Necessary	105.00 FS	*- FS
6	1		*BOOT LID CONTROL UNIT	Not Necessary	379.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Not Necessary	1,341.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION-CENTRE	Not Necessary	140.00 FS	*- FS
9	1		*REAR BUMPER HOLDING STRAP	Not Necessary	180.00 FS	*- FS
10	2		*REAR PARKING AID SENSOR-INNER/OUTER	Not Necessary	484.00 FS	*- FS
11	1		*TAIL LIGHT-LH	Cracked	355.00 FS	*283.60 FS
12	1		*EXHAUST TAIL PIPE TRIM-LH	Not Necessary	325.00 FS	*- FS
13	2		*REAR WHEEL COVER-LH/RH	Necessary	746.00 FS	*596.00 FS
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>8,837.00</b>	<b>4,301.20</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,350.00	600.00
3	TO RESPRAY REAR UPPER BUMPER,REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	3,000.00	1,600.00
4	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			<b>5,382.00</b>	<b>2,752.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >