

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012099/T1SD3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMTPSNA00000212000
Claimant Vehicle No :	EL23L	Insured Vehicle No :	SDX6336T
Date of Loss:	21/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D204103/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EL23L	Engine No:	32425774B38A15A
Make & Model:	BMW 118I, 1.5 (A)	Chassis No:	WBA7K320707E64370
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	10577 km
Colour:	Blue		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,118.60	1,673.25	445.35	21.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,092.00	2,084.00	1,008.00	32.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,210.60	3,757.25	1,453.35	27.89
+ GST 7.00/7.00% (S\$)	364.74	263.01	101.73	27.89
Nett Amount (S\$)	5,575.34	4,020.26	1,555.08	27.89

INSPECTION

Date of Assignment:	04/11/2020	
Date Inspected:	10/11/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2021)
Parts:	143	BMW 118I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EL23L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER PANEL PRIMED (LINES PDC)	Scratched	897.25 FS	*897.25 FS
2	1		*FRONT TOWING HITCH COVER	Serviceable	43.05 FS	*- FS
3	1		*FRONT GRILLE (LUXURY)	Scratched	696.00 FS	*696.00 FS
4	4		*DECOUPLING RING	Serviceable	20.40 FS	*- FS
5	1		*ULTRASONIC SENSOR MEDITERRANEAN BLU	Serviceable	381.90 FS	*- FS
6	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **2,118.60** **1,673.25**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER,FRONT RADIATOR GRILLE & ATTACHMENT ITEMS	New	1,700.00	850.00
2	TO RESPRAY PAINT FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING RECONNECT TO NEW BUMPER AND CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			3,092.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >