

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012100/UBA3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	COM0015
Claimant		
Vehicle No : SLA2771Y	Insured Vehicle No :	SH9943C
Date of Loss: 31/10/2020	Nature of Claim: TP	Claim No: MCT20100532

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA2771Y		
Make & Model:	CITROEN C4 CACTUS, 1.2 PureTech 82 (A)	Engine No:	10B2080374115
Reg. Date:	26/02/2016 (Man. Year: 2015)	Chassis No:	VF70PHMZBFE529799
Colour:	Red	Odometer:	62585 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,585.60	663.30	2,922.30	81.50
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	700.00	220.00	480.00	68.57
Paintwork Labour	400.00	200.00	200.00	50.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,696.60	1,094.30	3,602.30	76.70
+ GST 7.00/7.00% (S\$)	328.76	76.60	252.16	76.70
Nett Amount (S\$)	5,025.36	1,170.90	3,854.46	76.70
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
Nett Liability (S\$)		1,370.90		

INSPECTION

Date of Assignment:	05/11/2020	Present Location:	Progressive Car Care Pte Ltd (HQ)
Date Inspected:	13/11/2020	Inspected At:	Progressive Car Care Pte Ltd (HQ)
			Blk 3022A Ubi Road 1, #01-45/46
			Singapore 408716
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
Parts:	M1-SUV	CITROEN C4 CACTUS 1.2 PureTech 82 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA2771Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*REAR BUMPER	Repair	987.00 F	*- F
2	1	NA	*REAR BUMPER PAD	Cracked	634.00 F	*634.00 F
3	1	NA	*REAR BUMPER TOWING COVER - RH	Deformed	48.00 F	*48.00 F
4	4	NA	*REAR BUMPER SENSOR	Not Necessary	1,036.00 F	*- F
5	1	NA	*REAR BUMPER SENSOR WIRE	Not Necessary	683.00 F	*- F
6	1	NA	*REAR BUMPER REINFORCEMENT	Repair	321.00 F	*- F
7	1	NA	*REAR BUMPER TOP BEAM - PN9	Not Necessary	108.00 F	*- F
8	1	NA	*REAR BUMPER SIDE HOLDER	Not Necessary	112.00 F	*- F
9	10	NA	*REAR BUMPER CLIPS	Necessary	55.00 F	*55.00 F
					Sub Total (S\$)	3,984.00 737.00
					- Add. Disc. on L,N Items 10.00/10.00% (S\$)	398.40 73.70
					Total Parts (S\$)	3,585.60 663.30

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer) (NECESSARY)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	400.00	200.00
Labour Items				
2	TO KNOCK OUT DENTS; REMOVE; REPLACE ACCIDENT PARTS	New	450.00	150.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
5	TO RESET CHECK LIGHT	New	100.00	0.00
Gross Labour Cost (\$\$)			1,100.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >