

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20012101/DSD3Q2**Date:** 04/01/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00043392003

Claimant Vehicle No : YN4083P **Insured Vehicle No :** GBD8784Z

Date of Loss: 03/11/2020 Nature of Claim: TP Claim No: SNM20D204218/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN4083P**

Make & Model: ISUZU NNR85UH4A, 3.0 D (M) Engine No: 4JJ1372543

Reg. Date: 23/07/2013 (Man. Year: 2013) Chassis No: JAANNR85HD7100325

Colour: Blue Odometer: 252388 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85R16 Rear Tyre Size: 195/70R15(D)

Front Left Side: West Lake 5 mm Rear Left Side: Roadstone 5/5 mm

Front Right Side: West Lake 5 mm Rear Right Side: Roadstone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	28,843.06	7,437.66	21,405.40	74.21	
Miscellaneous Items	0.00	0.00	0.00		
Labour	6,950.00	1,820.00	5,130.00	73.81	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	35,793.06	9,257.66	26,535.40	74.14	
Approved Total (Overridden) (S\$)		7,400.00			
	(S\$)	35,793.06	7,400.00	28,393.06	79.33
	+ GST 7.00/7.00% (S\$)	2,505.51	518.00	1,987.51	79.33
	Nett Amount (S\$)	38,298.57	7,918.00	30,380.57	79.33

INSPECTION

Date of Assignment: 05/11/2020

Date Inspected: 06/11/2020 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Dec 2020)	
Parts:	N/A	ISUZU NNR85UH4A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN4083P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAIL LAMP LH/RH	Not Necessary	837.90 FL	*- FL
2	1		*TAIL LAMP WIRE HARNESS	Not Necessary	1,194.50 FL	*- FL
3	1		*TOW HOOK	Not Necessary	206.50 FL	*- FL
4	1		*REAR NO PLATE LAMP	Broken	119.48 FL	*80.25 FL
5	1		*FRONT WINDSCREEN	Cracked	1,895.39 FL	*1,538.20 FL
6	1		*FRONT WINDSCREEN MOULDING	Necessary	396.89 FL	*278.80 FL
7	2		*REAR DOOR LH/RH (50%)	Dented	5,600.00 FS	*2,800.00 FS
8	4		*REAR DOOR HINGES	Not Necessary	400.00 FS	*- FS
9	1		*60KM STICKER	Necessary	100.00 FS	*20.00 FS
10	1		*REAR NO PLATE	Bent	80.00 FS	*15.00 FS
11	1		*REAR CHASSIS CENTER PLATE	Bent	500.00 FS	*500.00 FS
12	1		*REAR WOODEN END PANEL (LOCAL REPAIR)	Cracked/Broken	1,000.00 FS	*200.00 FS
13	1		*REAR DOOR ADVERTISEMENT STICKER	Necessary	2,000.00 FS	*800.00 FS
14	2		*REAR DOOR INNER WOODEN PLANK	Not Necessary	2,000.00 FS	*- FS
15	2		*REAR DOOR LOCK	Bent/Damaged	600.00 FS	*300.00 FS
16	2		*REAR DOOR CATCH	Repair	400.00 FS	*- FS
17	1		*REAR DECK	Not Necessary	10,000.00 FS	*- FS
18	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
19	1		*FRONT WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
20	1		*REAR REINFORCEMENT BAR	Broken	1,400.00 FS	*800.00 FS
21	2		*REAR REINFORCEMENT BRACKET LH & RH	Bent	600.00 FS	*300.00 FS
22	8		*SCREW	Necessary/Dislodged	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	29,540.66	7,722.25
- List Item Discount on L Items 15.00/15.00% (\$\$)	697.60	284.59
Total Parts (\$\$)	28,843.06	7,437.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	3,000.00	1,400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	3,000.00	300.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
4	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	New	150.00	120.00
5	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
6	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$)			6,950.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >