

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012111/ATD3Q2

Date: 30/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00002472000
Claimant Vehicle No :	GBK1931A	Insured Vehicle No :	PC8458E
Date of Loss:	03/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204219/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK1931A	Engine No:	1KDB019190
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Chassis No:	KDY2318041243
Reg. Date:	03/02/2020 (Man. Year: 2019)	Odometer:	13545 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R13C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,152.50	4,235.50	5,917.00	58.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,450.00	1,970.00	2,480.00	55.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,602.50	6,205.50	8,397.00	57.50
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	14,602.50	4,900.00	9,702.50	66.44

INSPECTION

Date of Assignment:	05/11/2020	
Date Inspected:	05/11/2020 Inspected At:	Motoricarz Garage (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK Singapore 408934
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Nov 2020)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK1931A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	700.00 FL	*586.00 FL
2	1		*FRONT BUMPER SIDE COVER LH	Not Necessary	85.00 FL	*- FL
3	2		*FRONT BUMPER BRACKET	Not Necessary	225.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	190.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	75.00 FL	*- FL
6	1		*FRONT GRILLE	Cracked	550.00 FL	*550.00 FL
7	1		*FRONT GRILLE EMBLEM	Necessary	75.00 FL	*75.00 FL
8	1		*FRONT CORNER PANEL LH	Missing	475.00 FL	*385.00 FL
9	1		*FRONT HEADLAMP ASSY LH	Cracked	975.00 FL	*726.00 FL
10	1		*FRONT WINDSCREEN PILLAR LH	Repair	578.00 FL	*- FL
11	1		*FRONT SIDE MIRROR LH	Missing	296.00 FL	*296.00 FL
12	1		*FRONT SIDE ROUND MIRROR LH	Missing	899.00 FL	*384.00 FL
13	1		*FRONT WING MIRROR STAY	Missing	295.00 FL	*295.00 FL
14	1		*FRONT PILLAR LH	Repair	478.00 FL	*- FL
15	1		*FRONT PILLAR INNER GARNISH LH	Not Necessary	207.00 FL	*- FL
16	1		*FRONT PILLAR LOWER GARNISH LH	Not Necessary	175.00 FL	*- FL
17	1		*AIRCON BLOWER	Not Necessary	1,795.00 FL	*- FL
18	1		*FRONT DOOR PANEL LH	Dented	1,700.00 FL	*1,296.00 FL
19	1		*FRONT LH DOOR HINGE UPPER LH	Not Necessary	95.00 FL	*- FL
20	1		*FRONT LH DOOR HINGE LOWER LH	Not Necessary	95.00 FL	*- FL
21	1		*FRONT LH DOOR CHECKE LH	Not Necessary	150.00 FL	*- FL
22	1		*FRONT LH DOOR GLASS	Cut	726.00 FL	*726.00 FL
23	1		*FRONT LH DOOR GLASS REGULATOR	Not Necessary	358.00 FL	*- FL
24	1		*FRONT LH DOOR GLASS REGULATOR MOTOR	Not Necessary	580.00 FL	*- FL
25	1		*FRONT LH DOOR RUBBER	Cut	195.00 FL	*195.00 FL
26	1		*FRONT LH DOOR OUTER HANDLE	Not Necessary	193.00 FL	*- FL
27	1		*FRONT LH DOOR LOCK	Not Necessary	355.00 FL	*- FL
28	1		*FRONT LH DOOR INNER TRIM BOARD	Not Necessary	670.00 FL	*- FL
29	1		*SET FRONT BUMPER CLIP	Not Necessary	20.00 FS	*- FS
30	1		*SET FRONT GRILLE CLIP	Necessary	20.00 FS	*20.00 FS
31	1		*SET FRONT DOOR INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
32	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
33	1		*JOINT SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,450.00	5,614.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,297.50	1,378.50
Total Parts (\$\$)	10,152.50	4,235.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT FRONT WINDSCREEN	New	120.00	120.00
3	REMOVE AND REFIT FRONT DASHBOARD	New	500.00	0.00
4	REMOVE AND RENEW AIRCON BLOWER	New	150.00	0.00
5	REMOVE,REFIT TRIM,LINING AND GARNISH	New	200.00	80.00
6	TRANSFER PARTS,ATTACHMENT FROM OLD DOOR TO NEW	New	200.00	80.00
7	PANEL BEATING AND RENEW DAMAGE PARTS TO AFFECTED AREA	New	1,500.00	800.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	800.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	60.00
Gross Labour Cost (\$\$)			4,450.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >