

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012114/KQF3E2
Date: 25/02/2021

REFERENCE

Insured/Claimant: ANG SIU WAH Policy No: 2070138681
Date of Loss: 02/11/2020 Nature of Claim: OD Claim No: 8199147121SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE7752Z**
Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4031425
Reg. Date: 01/08/2016 (Man. Year: 2015) Chassis No: RU11111419
Colour: Metallic Pearl White Odometer: 127539 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$56,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,474.60	5,190.90	1,283.70	19.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,430.00	1,660.00	53.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,564.60	6,620.90	2,943.70	30.78
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	8,464.60	5,520.90	2,943.70	34.78
+ GST 7.00/7.00% (S\$)	592.52	386.46	206.06	34.78
Nett Amount (S\$)	9,057.12	5,907.36	3,149.76	34.78

INSPECTION

Date of Assignment: 05/11/2020
Date Inspected: 05/11/2020 Inspected At: Wega Engineering Pte Ltd (HQ)
BLK 176 Sin Ming Drive #04-16, Sin Ming AutoCare
Singapore 57521
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	380.00 F	*380.00 F
2	1		*FRONT BONNET HIAGE LH	Distorted	35.00 F	*35.00 F
3	1		*FRONT BONNET HIAGE RH	Distorted	35.00 F	*35.00 F
4	1		*FRONT BONNET INSULATION	Serviceable	75.00 F	*- F
5	1		*FRONT BONNET RUBBER	Serviceable	18.00 F	*- F
6	1		*FRONT BONNET LOCK	Distorted	75.00 F	*75.00 F
7	1		*FRONT BUMPER	Buckled	220.00 F	*220.00 F
8	1		*FRONT BUMPER TOWING COVER	Serviceable	12.00 F	*- F
9	1		*FRONT BUMPER REFORCEMENT	Bent	220.00 F	*220.00 F
10	1		*FRONT BUMPER RENTANNAL LH	Distorted	15.00 F	*15.00 F
11	1		*FRONT BUMPER RENTANNAL RH	Serviceable	15.00 F	*- F
12	1		*FRONT BUMPER LOWER SKIRT	Buckled	180.00 F	*180.00 F
13	1		*FRONT BUMPER LOWER GRILLER	Cracked	48.00 F	*48.00 F
14	15		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 F
15	1		*FRONT FOG LAMP	Serviceable	145.00 F	*- F
16	1		*FRONT FOG LAMP COVER	Serviceable	18.00 F	*- F
17	1		*FRONT RADIATOR BASE	Serviceable	220.00 F	*- F
18	1		*FRONT RADIATOR OUTER	Serviceable	170.00 F	*- F
19	2		*FRONT GRILLER RADIATOR (CHROME)	Cracked	480.00 F	*480.00 F
20	1		*FRONT GRILLER EMBLEM LOGO	Not Necessary	18.00 F	-
21	1		*FRONT HEADLAMP LH	Mtg Broken	880.00 F	*880.00 F
22	1		*FRONT HEADLAMP RH	Mtg Cracked	880.00 F	*880.00 F
23	1		*FRONT HEADLAMP BRACKET LH	Cracked	24.00 F	*24.00 F
24	1		*FRONT HEADLAMP BRACKET RH	Cracked	24.00 F	*24.00 F
25	1		*FRONT SUPPORT PANEL	Bent	350.00 F	*350.00 F
26	1		*FRONT SUPPORT TOP GARNISH	Serviceable	48.00 F	*- F
27	1		*FRONT SUPPORT TOP BRACKET	Distorted	48.00 F	*48.00 F
28	1		*FRONT RADIATOR AIR DUCT RH	Serviceable	22.00 F	*- F
29	1		*FRONT RADIATOR AIR DUCT LH	Serviceable	22.00 F	*- F
30	1		*FRONT AIR COND	Bent / Punctured	250.00 F	*250.00 F
31	1		*FRONT RADIATOR	Punctured	520.00 F	*520.00 F
32	1		*FRONT FAN COWLING	Serviceable	66.00 F	*- F
33	1		*FRONT A/C FAN BLADE	Serviceable	45.00 F	*- F
34	1		*FRONT RADIATOR BLADE	Serviceable	45.00 F	*- F
35	1		*FRONT A/C FAN MOTOR	Serviceable	114.00 F	*- F
36	1		*FRONT RADIATOR FAN MOTOR	Serviceable	114.00 F	*- F
37	1		*CLAMP A FUEL HOSE	Necessary	5.00 F	*5.00 F
38	1		*CLIP- AMBIENT SENSOR BRACKET	Necessary	15.00 F	*15.00 F
39	1		*BONNET STONE CLIP	Necessary	5.00 F	*5.00 F

F=Franchise part.

Sub Total (S\$)	5,886.00	4,719.00
+ Margin on L,N Items 10.00/10.00% (S\$)	588.60	471.90
Total Parts (S\$)	6,474.60	5,190.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & SYSTEM FUNCTION.	New	100.00	20.00
2	TO REMOVE & REFIX RADIATOR, AIRCOND CONDENSER & FAN SYSTEM.}	New	280.00	100.00
3	TO VACUUM & CHARGE AIRCON R134 GAS.}	New	60.00	0.00
4	TO INSPECT REAR MECHANISMS & WATER TEST REAR LEAKING.	New	150.00	0.00
5	TO FLUSHING & TOP UP RADIATOR WATER COOLANT.	New	80.00	50.00
6	TO CHECK HEADLAMP LIGHTING ALIGNMENT.	New	120.00	0.00
7	TO REPLACE, KNOCKING ACCIDENT FRONT BONNET, BUMPER, SUPPORT PANEL, FENDER LH & RH.	New	1,300.00	600.00
8	TO RESPRAY FRONT PORTION, BONNET, BUMPER, SUPPORT PANEL & FENDER LH & RH.	New	1,000.00	660.00
			Gross Labour Cost (S\$)	3,090.00
				1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >