

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012118/DBA3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100354113
Claimant Vehicle No :	SKR4281D	Insured Vehicle No :	SFD9781C
Date of Loss:	04/11/2020	Nature of Claim:	TP
		Claim No:	3585462847SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR4281D	Engine No:	3ZRB452237
Make & Model:	TOYOTA HARRIER, 2.0 ELEGANCE CVT (A)	Chassis No:	ZSU600025796
Reg. Date:	06/02/2015 (Man. Year: 2014)	Odometer:	103754 km
Colour:	Silver		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,877.72	4,484.82	20,392.90	81.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	1,820.00	3,630.00	66.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,327.72	6,304.82	24,022.90	79.21
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	30,327.72	5,000.00	25,327.72	83.51
+ GST 7.00/7.00% (S\$)	2,122.94	350.00	1,772.94	83.51
Nett Amount (S\$)	32,450.66	5,350.00	27,100.66	83.51
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,226.45		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 05/11/2020

Date Inspected: 06/11/2020 Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
 AutoPoint
 Singapore 568047

2/16/2021

Adjuster Report

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,054.25 FL	*1,712.05 FL
2	1		*TAILGATE LOCK	Not Necessary	188.00 FL	*- FL
3	1		*TAILGATE INNER LOCK	Not Necessary	892.65 FL	*- FL
4	1		*TAILGATE STRIKER LOCK	Not Necessary	60.45 FL	*- FL
5	1		*TAILGATE INNER TRIM BOARD	Not Necessary	637.65 FL	*- FL
6	1		*TAILGATE HARRIER EMBLEM	Not Necessary	72.66 FL	*- FL
7	1		*TAILGATE LOGO	Necessary	100.05 FL	*75.10 FL
8	1		*TAILGATE CENTER GARNISH	Not Necessary	682.90 FL	*- FL
9	2		*TAILGATE LAMP LH/RH	Not Necessary	1,236.60 FL	*- FL
10	2		*TAILGATE NO.PLATE LAMP LH/RH	Not Necessary	188.70 FL	*- FL
11	2		*TAILGATE WINDSCREEN MOULDING	Necessary	270.60 FL	*270.60 FL
12	1		*TAILGATE INNER HANDLE	Not Necessary	28.65 FL	*- FL
13	1		*TAILGATE SWITCH	Not Necessary	220.50 FL	*- FL
14	2		*TAIL LAMP LH/RH	Not Necessary	1,206.30 FL	*- FL
15	2		*TAIL LAMP PANEL LH/RH	Not Necessary	465.30 FL	*- FL
16	1		*REAR BUMPER	Distorted	2,071.65 FL	*1,395.30 FL
17	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	277.00 FL	*- FL
18	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	98.00 FL	*- FL
19	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	332.00 FL	*- FL
20	1		*REAR BUMPER SPONGE	Broken	175.80 FL	*175.80 FL
21	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	190.70 FL	*- FL
22	1		*REAR BUMPER LOWER	Distorted / Cut	603.21 FL	*603.21 FL
23	1		*REAR BUMPER UNDERCOVER	Not Necessary	210.92 FL	*- FL
24	1		*REAR REINFORCEMENT BAR	No such part	872.49 FL	*- FL
25	1		*REAR END PANEL	Dented	1,072.95 FL	*803.10 FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	529.53 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH CHROME	Not Necessary	188.92 FL	*- FL
28	1		*REAR END PANEL SENSOR BUZZER	Mtg Broken	178.83 FL	*178.83 FL
29	1		*REAR END PANEL ANTENNA RECEIVER	Not Necessary	221.47 FL	*- FL
30	1		*SPARE WHEEL PANEL	Not Necessary	1,054.92 FL	*- FL
31	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	1,048.65 FL	*- FL
32	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	817.18 FL	*- FL
33	2		*SPARE WHEEL SIDE CONTAINER LH/RH	Not Necessary	2,280.56 FL	*- FL
34	1		*SPARE WHEEL PANEL TOP MAT	Not Necessary	980.42 FL	*- FL
35	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	608.85 FL	*- FL
36	2		*REAR FENDER LH/RH	Not Necessary	3,360.00 FL	*- FL
37	2		*REAR FENDER INNER TRIM LH/RH	Not Necessary	2,145.90 FL	*- FL
38	1		*REAR EXHAUST PIPE	Not Necessary	1,351.82 FL	*- FL
39	1		*REAR EXHAUST MOUNTING	Not Necessary	69.25 FL	*- FL
40	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	199.92 FL	*- FL
41	1		*REAR EXHAUST PIPE GASKET	Not Necessary	30.17 FL	*- FL
42	1		*REAR EXHAUST MID PIPE	Not Necessary	2,194.82 FL	*- FL
43	1		*TAILGATE WEATHERSTRIP	Deformed	299.10 FL	*299.10 FL
44	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
45	1		*REAR WINDSCREEN DAMPING SEAL	Necessary	50.00 FS	*20.00 FS
46	1		*REAR NO PLATE & CASING	Not Necessary	50.00 FS	*- FS
47	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*TAILGATE CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
50	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
51	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
53	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
54	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
55	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
56	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
57	1		*REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	32,820.29	5,863.09
- List Item Discount on L Items 25.00/25.00% (\$\$)	7,942.57	1,378.27
Total Parts (\$\$)	24,877.72	4,484.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	500.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,600.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,600.00	700.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	30.00
5	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	80.00
6	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
7	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
8	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			5,450.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >