Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20012122/UYF3Q2

Date: 17/11/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29141713

Claimant Vehicle No: SKL7247R Insured Vehicle No: SLT9263B

Date of Loss: 05/11/2020 Nature of Claim: TP Claim No: 630626

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL7247R

 Make & Model:
 TOYOTA VELLFIRE, 2.4 Z G-Edition (A)
 Engine No:
 2AZG256132

 Reg. Date:
 18/12/2013 (Man. Year: 2013)
 Chassis No:
 ANH208299191

 Colour:
 Black
 Odometer:
 295604 km

Engine Capacity: 2362 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,174.26	7,588.92	11,585.34	60.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	1,980.00	830.00	29.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,984.26	9,568.92	12,415.34	56.47
Approved Total (Overridden) (S\$)		7,600.00		
(S\$)	21,984.26	7,600.00	14,384.26	65.43
+ GST 7.00/7.00% (S\$)	1,538.90	532.00	1,006.90	65.43
Nett Amount (S\$)	23,523.16	8,132.00	15,391.16	65.43

INSPECTION

Date of Assignment: 16/11/2020

Date Inspected: 05/11/2020 Inspected At: Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2020)		
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 Z G-Edition (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SKL7247R)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	87.60 F	*87.60 FL
2	1		*TAILGATE	Badly Dented	1,806.23 F	*1,755.10 FL
3	1		*TAILGATE VELLFIRE EMBLEM	Necessary	78.00 F	*78.00 FL
4	1		*TAILGATE WEATHERSTRIP	Twisted	387.00 F	*322.10 FL
5	1		*TAILGATE INNER LOCK	Shorted/Jammed	509.23 F	*409.20 FL
6	1		*TAILGATE INNER TRIM BOARD	Deformed/Cracked	784.00 F	*699.50 FL
7	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 F	*60.00 FL
8	2		*TAILGATE REFLECTORS	Cracked	1,378.00 F	*782.40 FL
9	1		*TAILGATE OUTER CHROME GARNISH	Cracked	785.10 F	*588.20 FL
10	1		*REAR BUMPER	Distorted	1,450.00 F	*845.10 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	190.00 F	*-FL
12	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
13	1		*REAR BUMPER TOW COVER	Torn	48.00 F	*48.00 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	190.00 F	*- FL
15	1		*REAR END PANEL	Badly Dented	862.00 F	*845.10 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	195.00 F	*195.00 FL
17	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 F	*-FL
18	2		*REAR FENDER INNER TRIM BOARDS	Deformed/Torn	1,696.20 F	*1,510.20 FL
19	1		*SET REAR FENDER INNER TRIM BOARDS CLIPS	Not Necessary	60.00 F	*-FL
20	2		*TAILLAMPS	Not Necessary	2,102.40 F	*- FL
21	2		*TAILLAMP LOWER GARNISHS	Repair	730.00 F	*-FL
22	1		*REAR FLOOR PANEL	Repair	1,125.20 F	*-FL
23	1		*REAR FLOOR PANEL CLOTH	Not Necessary	866.10 F	*-FL
24	1		*REAR FLOOR PANEL TOP BOARD N/S	Not Necessary	655.10 F	*-FL
25	1		*REAR BUMPER UNDER SPLASH N/S	Not Necessary	315.10 F	*-FL
26	1		*REAR BUMPER PDC SENSORS (4 Pcs)	Shorted (2 Pcs only)	1,060.00 F	*530.00 FL
27	1		*REAR ANTENNA SENSOR	Cracked	345.50 F	*291.10 FL
28	1		*REAR BUZZLE SENSOR	Cracked	288.50 F	*225.30 FL
29	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
30	1		*REAR LICENCE PLATE W/HOLDER	Serviceable	50.00 FS	*-FS
31	1		*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*300.00 FS
32	1		*REAR BUMPER TOP CHROME MOULDING	Bent	500.00 FS	*200.00 FS
33 F=Fra	1 anchise	part S=9	*REAR END PANEL SEALANT SpcNett. L=ListItemDisc.	Necessary	50.00 FS	*50.00 FS
	Sub Total (S\$				19.174.26	9,921.90
	- List Item Discount on L Items 0.00/25.00% (S\$)				2,332.98	
				Total Parts (S\$)	19,174.26	7,588.92

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
4	TO REMOVE & REFIX REAR CUSHION UPHOLSTERY	New	150.00	80.00
5	TO SPRAY RUST PROOFING	New	150.00	60.00
6	TO REMOVE & REPLACED PDC SENSOR	New	60.00	50.00
7	TO CUT,WELD,STRAIGHTEN,REALIGN & REPLACED PARTS	New	980.00	680.00
8	TO PUTTY & SPRAY PAINTING	New	1,200.00	900.00
	Gross Labour Cost (S\$)		2,810.00	1,980.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.