ASS. REC. BY: REF: A/G /	
ennerh	20012126/K+
	ASSIGNMENT
	The transfer of the transfer o
Csornated Cost:	Veh No: 68/1 862/6 Yr Regn: 08, 18
TO INSPECT VALUE AND THE STORY OF THE STORY	Type: M.Car / M.Cycle / Bus / Van) Lorry / Taxl / Prime Mover /
webect Aguide No:	Truck / Traller or
at Workshop m/s Tang Luck	Make: Mer Vito 114 CDic 2143
of lang. Luck	Colour M. Black AC: Insured Std NI NA
Insured:	Sp.Reading 96679 T/Radlo: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: WDF 44760323351834
Sum Insured:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: Nii / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 215/60R16
Pemark: The veh had commerced to	R:
repair at the time of inspection.	BS / DON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value: 872k	TOYO/YOKO or Dable Sta
IDAC Accident Rport: Consistent?: Yes or No	Fron! Rear
GIA / PR Seen: Consistent?: Yes or No	R/Bal. 9 mm R/Bal. 9 mm
Est. Repairs: 4-6 days Res.: Yes or No	D.O.A. 23/9/20 DOL 5
Lum Sum: 1-B. / % 3 Val.: Yes or No	11/1/10/20
CA I REV I REP. I 24 HRS	Survey held at
Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
reison Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
PART BY PART \$3554, 4DAY	C
<u> </u>	
RED 4597.55;56%	
Onto/Timo, Fag Pass to? : Prell. Report	1
1)	Days Of Repair: 4
Oute/1 me, File Return to?	Resurvey No. of Trip: Survey Fee:
Add Fee:	Transmission
•	S.RS SI
Report Format :	Interview (S), For a
Lump Sum / I.B.I: (3	Tech Invs (\$) Others
	Weekend (\$
	1074



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN: MOTOR CLAIM DEPT

TEL : 6419 3000

Accord B4 paint
FAX: 6415 3723
4-6day

YOUR REF NO **CLAIM TYPE** : OWN DAMAGE

ACCIDENT DATE : 23/09/2020

ESTIMATE

: QUOT202010-000005(00) NO

DATE : 02/10/2020 POLICY NO : 999995580

VEH REG NO : GBH6621C MAKE/MODEL : MERCEDES BENZ VITO 114 CDI PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323351834

ENGINE NO : 65195034274310

: 2018 REG. DATE

Estimate Repair Cost to Vehicle No: GBH6621C

18 To transfer damaged tailgate interior mechanism to new tailgate. 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same.		Description	Quai	ntity	Unit P	rice		Amount	
1 Tailgate 2 Tailgate centre logo 1 48.00		A.				<u>S\$</u>		<u>S\$</u>	
Tailgate centre logo					4.056		R	1 250 00	۷
Tailgate 'VITO' emblem				1				•	
4 Tailgate 'C&C' emblem 5 Tailgate '109 CDI' emblem 6 Tailgate '109 CDI' emblem 7 Tailgate '109 CDI' emblem 1				1					٠
5 Tailgate '109 CDI' emblem 1 62.00 1 62.00 1 62.00 1 62.00 1 62.00 1 550.00 1 550.00 1 550.00 1 550.00 1 550.00 1 550.00 1 550.00 1 8 550.00 1 8 850.00 1 8 850.00 1 8 850.00 1 8 850.00 1 8 850.00 1 8 850.00 1 8 850.00 1 8 850.00 1 8 850.00 1 7 80.00 1 8 850.00 1 8 850.00 1 7 80.00 1 8 850.00 1 7 80.00 1 3 910.55 1 1 1 1 4 1 3 910.55 1 1 1 3 1 1 3 1 3 1 3 1 3 1	00000	2 - 19 - 19 - 19 - 19 - 19 - 19 - 19 - 1		1			1		
6 Taillamp assy - LH 7 Taillamp lower garnish - LH 8 Rear bumper 9 Rear bumper clips 10 Rear fender - LH 10 Rear fender - LH 11				1			IVEC.		
Taillamp lower garnish - LH				20.00			200		
8 Rear bumper 1		N 5							
Rear bumper clips LKK Auto Consultants hence notify 1 the Repairer of the following: To resurvey before/after spray painting	7						C100	00.00	•
LKK Auto Consultants hence notify 1 the Repairer of the following: **To display damaged perfs, during resurvey **Parts prices are subject to confirmation **To hid party survey is on a "Without Prejudice" basis **No illegal modification(s) is allowed 1 **Supplementary item(s) must be resurveyed and 1 is subject to final approval from Insurance Company **LABOUR** LABOUR** **To remove and refit rear windscreen glass.** **To remove and refit rear bumper sensor** To check and rectify wiring system** To transfer damaged tailgate interior mechanism to new tailgate.** To remove and refit LH fender interior garnishes and trimboard, to 1 facilitates the repairs To panel beat and straighten rear floorboard panel, rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same.** **LABOUR** **To putly and spray paint on affected areas** **LKK Auto Consultants hence notify 1 the Repairing 3,910.50 **Add 10%** 3,910.50 4,301.55 **Add 10%** 3,910.50 4,301.55 **Add 10%** 3,910.50 4,301.55 **Add 10%** 391.05 4,301.55 **Add 10%** 4,301.50 60.00 60	8	A TOTAL CONTRACTOR OF THE CONTRACTOR OF T		1870		.00	,		5
the Répairer of the following: • To resurvey beforefalter spray painting • To disp/ay damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed 1			LKK Auto Consultation	15	_ ~~ 5	.50	1000	82.50	_
SPECIAL NET 11 Rear windscreen sealant 12 Tailgate '6 pax' sricker 13 Tailgate '70km/h' sticker 14 Rear bumper sensor LABOUR 15 To remove and refit rear windscreen glass. 16 To remove and refit rear bumper sensor 17 To chcek and rectify wiring system 18 To transfer damaged tailgate interior mechanism to new tailgate. 19 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 10 To putty and spray paint on affected areas 11 To putty and spray paint on affected areas 11 To putty and spray paint on affected areas 12 To display damaged part(s) during resurvey 13 Add 10% 391.50 4,301.55 4,301.65 4,301.65 4,301.65 4,301.65 4,301.65 4,301.65 4,301.65 4,301.65 4,301.65 4,301.6	10	Rear fender - LH	the Repairer of the following:	1	780	.00	R	780.00	
SPECIAL NET 11 Rear windscreen sealant 12 Tailgate '6 pax' sricker 13 Tailgate '70km/h' sticker 14 Rear bumper sensor 15 To remove and refit rear windscreen glass. 16 To remove and refit rear bumper sensor 17 To chcek and rectify wiring system 18 To transfer damaged tailgate interior mechanism to new tailgate. 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 10 Conditional Time Parts survey is on a "Without Prejudice" basis 10 Action of a "Without Prejudice" basis 11 Consider data of the continuation of the resurveyed and the surveyed and t			 To resurvey before/after spray painting 		1				
SPECIAL NET 11 Rear windscreen sealant 12 Tailgate '6 pax' sricker 13 Tailgate '70km/h' sticker 14 Rear bumper sensor LABOUR 15 To remove and refit rear windscreen glass. 16 To remove and rectify wiring system 17 To chcek and rectify wiring system 18 To transfer damaged tailgate interior mechanism to new tailgate. 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 10 To putty and spray paint on affected areas 11 To putty and spray paint on affected areas 12 Tailgate '6 pax' sricker 13 Sound 15 Cond 25 Cond 26 Cond 25 Cond 25 Cond 25 Cond 26 Cond 25 Cond 25 Cond 25 Cond 25 Cond 25 Cond 26 Cond 25 Cond 26 Cond 25 Cond 26 Cond 25 Cond 26			 Io display damaged part(s) during recursion 		Add	10%			
11 Rear windscreen sealant 12 Tailgate '6 pax' sricker 13 Tailgate '70km/h' sticker 14 Rear bumper sensor LABOUR 15 To remove and refit rear windscreen glass. 16 To remove and rectify wiring system 17 To chcek and rectify wiring system 18 To transfer damaged tailgate interior mechanism to new tailgate. 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 10 Supplementary item(s) must be resurveyed and 1 25.00		SPECIAL NET	Third party survey is on a "Without Project to a "I		0.1		4	4,301.55	
12 Tailgate '6 pax' sricker 13 Tailgate '70km/h' sticker 14 Rear bumper sensor LABOUR 15 To remove and refit rear windscreen glass. 16 To remove and rectify wiring system 17 To chcek and rectify wiring system 18 To transfer damaged tailgate interior mechanism to new tailgate. 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 10 Sput Panel	11		two inegal modification(s) is allowed	4	60	00		60.00	
13 Tailgate '70km/h' sticker 14 Rear bumper sensor LABOUR 15 To remove and refit rear windscreen glass. 16 To remove and refit rear bumper sensor 17 To chcek and rectify wiring system 18 To transfer damaged tailgate interior mechanism to new tailgate. 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 1 1,200.00 25.00 26.00 27.00 28.00 29.00 20.00	12	Tailgate '6 pax' sricker	Supplementary item(s) must be resurveyed and is subject to final approval from the	1 1	1		ne		1
Acknowledged by Repairer Signature: Date: LABOUR 15 To remove and refit rear windscreen glass. 1 150.00 150.00 1 To remove and refit rear bumper sensor 1 100.00 100.00 5 To chcek and rectify wiring system 1 80.00 80.00 2 18 To transfer damaged tailgate interior mechanism to new tailgate. 1 150.00 150.00 6 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 1 1,200.00 1,200.00	13	- Mar 1		pany 1					
LABOUR 15 To remove and refit rear windscreen glass. 1 150.00 150.00 1 16 To remove and refit rear bumper sensor 1 100.00 100.00 5 17 To check and rectify wiring system 1 80.00 80.00 2 18 To transfer damaged tailgate interior mechanism to new tailgate. 1 150.00 150.00 6 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 1 1,200.00 1,200.00	14		Acknowledged by Repairer	1	1	4500			
LABOUR To remove and refit rear windscreen glass. 1 150.00 150.00 1 To remove and refit rear bumper sensor 1 100.00 100.00 5 To check and rectify wiring system 1 80.00 80.00 2 To transfer damaged tailgate interior mechanism to new tailgate. 1 150.00 150.00 6 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 1 1,200.00 1,200.00		Acceptance of the second secon	The state of the s	•	300	- 00			
16 To remove and refit rear bumper sensor 17 To chook and rectify wiring system 18 To transfer damaged tailgate interior mechanism to new tailgate. 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 11 1,200.00 1,200.00		LABOUR			W _a ,			490.00	
To remove and refit rear bumper sensor 1 100.00 100.00 5 17 To chock and rectify wiring system 1 80.00 80.00 2 18 To transfer damaged tailgate interior mechanism to new tailgate. 1 150.00 150.00 6 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 1 1,200.00 1,200.00	15	To remove and refit rear windscreen g	lass.	1	150	.00		150.00	1
To check and rectify wiring system 1 80.00 80.00 2 18 To transfer damaged tailgate interior mechanism to new tailgate. 1 150.00 150.00 6 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 1 1,200.00 1,200.00	16	To remove and refit rear bumper sense	or	1	100	.00			
To transfer damaged tailgate interior mechanism to new tailgate. 1 150.00 150.00 6 19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs 20 To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. 21 To putty and spray paint on affected areas 1 150.00 18	17	To cheek and rectify wiring system		1	80	.00			
To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs To panel beat and straighten rear floorboard panel. rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. To putty and spray paint on affected areas 1 1,200.00 1,200.00	18	To transfer damaged tailgate interior n	nechanism to new tailgate.	1					
To panel beat and straighten rear floorboard panel, rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same. To putty and spray paint on affected areas 1 1,500.00 1,500.00 2	19	To remove and refit LH fender interior facilitates the repairs	garnishes and trimboard, to	1					
21 To putty and spray paint on affected areas 1 1,200.00 1,200.00	20	To panel beat and straighten rear floor frame, rear LH fender inner panel, to c including replacement of parts and alic	ut and weld LH fender.	1	1,500	.00	1	,500.00	
3,360.00	21		eas	1	1,200.	.00	1	,200.00	0
						-	3	,360.00	

MBHH20083821-01 / Ajax Mars Pte Ltd - Bukit Merah ENTRY DATE & TIME: 26/09/2020 00:23 SUBMITTED BY: Muhammad Sumardi Bin Mohd Affandi

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 04/11/2020 18:26

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability. repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

400	DENIT	CTA	-	ENT
ACCI	DENI	2	- 11	-

26/09/2020 00:23 Date Of Report 23/09/2020 16:30 Date Of Accident

LEVEL 2 NORTHLINK MULTI STOREY CARPARK. **Exact Location Of Accident**

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

GBH6621C Vehicle Registration Number

Insured/Policyholder

DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Name Of Registered Owner

1XXXXX778Z Co Reg No

BENNY.CHONG@DAIMLER.COM **Email Address**

Mobile Phone No

OFFICE-68498118 Alternative Phone No

Vehicle Particulars

MERCEDES-BENZ Manufacturer

VITO 114 CDI PANEL VAN LONG AT ABS 5DR Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

PRIVATE CAR Vehicle Category

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE, LTD.

COMPREHENSIVE Type Of Coverage

Fleet Policy YES Policy Number 999995580

Cover Note Number

Driver

Name of Driver SUBRAMANIYAN MANIKANDAN

NRIC No GXXXX787K Date Of Birth 01/02/1993 Occupation OUTDOOR **Date Of Driving Pass** 27/11/2017

Driving Experience 2 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90606506

Fax Number

Contact Number

EMail Address SMAMIKANDAN220@GMAIL.COM

Page 1 of 23

Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

NA

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON THE DATE AND TIME MENTIONED I HAD PARKED MY VEHICLE AT THE SAID LOCATION WHEN IT WAS HIT BY A MOVING VEHICLE B, I HAD ASKED THE PARTICULARS OF THE DRIVER OF VEHICLE B, BUT THE DRIVER DID NOT GIVE ME ANY PARTICULARS AND MOVED AWAY FROM THE ACCIDENT SCENE. THERE IS A SECURITY CAMERA IN THE

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

XD2328L

Vehicle Make/Model/Colour

MITSUBISHI / FV51JP4RDEA

Details Of Properties

NA

NA

Vehicle Category Name of Driver

COMMERCIAL VEHICLE

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 23

SKETCH PLAN	ahari	29	
4: GH16621C	COLUMN A		
P: XD3338T	Mr.		
	1 ever 2.1	MODING MS/CP.	
DESCRIBE CIRCUMSTANCES			
REFER TO ATTACHED STAT	EMENT.		
	13		
		9	
3 200			
-	1000	GMs.	
DECLARATION (We declare the foregoing partic	cular ara trus la sur cui a	No. 1912	
OME detrace the integrand batta	X every respect.	VERIFY BY AJAX MARS (ARC) REPORTING OFFICER	
	- Vistorial	HASHIM BIN KAMARI	



CCIDENT STATEMENT (2000 characters)	
PARTICULARS OF THE DRIVER OF ME ANY PARTICULARS AND MOVE	IED I HAD PARKED MY VEHICLE AT THE SAID MOVING VEHICLE B, I HAD ASKED THE VEHICLE B, BUT THE DRIVER DID NOT GIVE D AWAY FROM THE ACCIDENT SCENE. I THE BUILDING AND MY COMPANY
	*
	1,000
	() ()
	8
Taxi Voucher No.:	
I/We declare that the above particulars & information pro	ovided above are true in every aspect
VERIFIED BY AJAX MARS REPORTING OFFICER - HASHIM BIN KAMARI	
	3000
MARS Officer	
	Registered Owner or Driver's Signature
Job Complete Date/Time	Date/Time:
24 September 2020 at 6:46 PM	25 September 2020 at 6:46 AM

Page 5 of 23