Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012127/QGS3Q2

Date: 27/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070032789

Claimant Vehicle No: Insured Vehicle No: FBQ8256M

Date of Loss: 04/11/2020 Nature of Claim: TP Claim No: 0963939792SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG2294B

 Make & Model:
 HONDA SHUTTLE HYBRID, 1.5 (A)
 Engine No:
 LEB4259960

 Reg. Date:
 23/09/2016 (Man. Year: 2016)
 Chassis No:
 GP71040652

 Colour:
 Silver
 Odometer:
 267775 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,231.28	2,148.24	3,083.04	58.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,080.00	1,280.00	54.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,591.28	3,228.24	4,363.04	57.47
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	7,591.28	2,600.00	4,991.28	65.75
+ GST 7.00/7.00% (S\$)	531.39	182.00	349.39	65.75
Nett Amount (S\$)	8,122.67	2,782.00	5,340.67	65.75
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/S	2.00			
Ne	2,934.00			

INSPECTION

Date of Assignment: 05/11/2020

Date Inspected: 05/11/2020 Inspected At: Lion City Rentals Pte Itd (HQ)

1090 LOWER DELTA ROAD #05-12

Singapore 169201

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR TAILGATE	Dented	1,850.00 FL	*1,200.00 FL		
2	1		*REAR TAILGATE LOCK	Serviceable	550.00 FL	*- FL		
3	1		*REAR TAILGATE LOCK CATCH	Serviceable	158.00 FL	*- FL		
4	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*151.00 FL		
5	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	255.00 FL	*- FL		
6	1		*REAR TAILGATE HONDA EMBLEM	Serviceable	81.30 FL	*- FL		
7	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	88.40 FL	*88.40 FL		
8	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	88.40 FL	*88.40 FL		
9	1		*REAR BUMPER	Crumpled	1,350.00 FL	*820.00 FL		
10	1		*REAR BUMPER RH TOW COVER	Serviceable	68.00 FL	*- FL		
11	1		*REAR END PANEL	Serviceable	950.00 FL	*- FL		
12	1		*REAR END PANEL TOP COVER	Serviceable	180.00 FL	*- FL		
13	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS		
14	1		*SET WINDSCREEN SELANT	Necessary	120.00 FS	*40.00 FS		
15	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS		
16	1		*SET END PANEL TOP GARNISH CLIPS	Serviceable	80.00 FS	*- FS		
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.							
				Sub Total (S\$)	6,394.10	2,617.80		
	- List Item Discount on L Items 20.00/20.00% (S\$)			1,162.82	469.56			
				Total Parts (S\$)	5,231.28	2,148.24		
	Report was unsubmitted during this print-out.							
	Troport was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT ,CUT/WELD ,STRAIGHTEN PANEL WHERE STRAIGHTEN	New	900.00	500.00				
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	900.00	400.00				
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	160.00	120.00				
4	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00				
5	TO TRANSGER TAILGATE MECHANISM	New	100.00	60.00				
	Gross Labour Cost (S\$)		2,360.00	1,080.00				
	Report was unsubmitted durir	ng this print-out.						

< END OF ESTIMATES >