

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012133/ACD3E2

Date: 18/03/2021

REFERENCE

Insured/Claimant:	AZIZAH BINTI JAON	Policy No:	2070139930		
Date of Loss:	31/10/2020	Nature of Claim:	OD	Claim No:	8612187648SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC335B		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZDC05363
Reg. Date:	30/09/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF3XM1008431
Colour:	White	Odometer:	807 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,539.40	3,011.60	1,527.80	33.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,372.00	1,922.00	3,450.00	64.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,911.40	4,933.60	4,977.80	50.22
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	9,111.40	4,133.60	4,977.80	54.63
+ GST 7.00/7.00% (S\$)	637.80	289.35	348.45	54.63
Nett Amount (S\$)	9,749.20	4,422.95	5,326.25	54.63

INSPECTION

Date of Assignment:	05/11/2020		
Date Inspected:	05/11/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RH	Dented	2,553.00 FS	*2,042.40 FS
2	1		*REAR DOOR OUTER SEAL - RH	Necessary	134.00 FS	*106.80 FS
3	1		*REAR DOOR CATCH	Damaged	119.00 FS	*94.80 FS
4	1		*SILL PANEL SEAL - RH	Not Necessary	134.00 FS	*- FS
5	1		*REAR DOOR COVER - RH	Cut	345.00 FS	*276.00 FS
6	1		*FRONT DOOR COVER - RH	Not Necessary	366.00 FS	*- FS
7	1		*REAR WHEEL COVER - RH	Cut	530.00 FS	*424.00 FS
8	1		*AUDI RING STICKER	Necessary	58.40 FS	*58.40 FS
9	1		*SUNDRIES	Necessary	300.00 FS	*9.20 FS
Total Parts (S\$)					4,539.40	3,011.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	400.00	0.00
2	TO REMOVE AND TRANSFER REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
3	TO DISMANTLE AND RENEW RHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, DOOR COVERS AND RHS REAR WHEEL ARCH TRIM	New	3,300.00	950.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,372.00	1,922.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >