

From: jenny chong <jenny@esteemperf.com.sg>
Sent: Saturday, 11 April 2020 1:57 PM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com.sg>
Cc: carmen lim <carmenlim@lkkauto.com.sg>

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

K. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31496

Date : 30-Oct-2020

PAGE : 1

Vehicle Insured : GBE 9998 L
Accident Date : 18-Sep-2020

Our Ref : 020446 (CHINA) / QUEK

DS CAR RENTAL PTE LTD
Singapore

ESTIMATED COST OF REPAIR FOR TOYOTA DYNA 150(M)(2982cc)(2015) GBE3643A
=====

Repair and retrofit freezer box
parts and fixtures
Supply and replace one lot
aluminium extrusion capping c/w
structure bonding and sealant
(RH side lower parts)
Supply and replace one portion
rear door stainless steel frame
c/w bonding and T.I.G welding
Supply and replace one rear door
hinges (LH) adjust and realign
freezer box doors
Supply labour and services

2100
2,950.00

Total : S\$ 2,950.00
=====

Singapore Dollars Two Thousand Nine Hundred and
Fifty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

NOT Authorized
Repairing After Paint
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: