

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STZ 1372P Yr Regn: 10, 10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M/C180 c.c. 1796

Colour:

M/D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

172.421

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2040 492A 384 536

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40 8R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

2/11/20

D.O.I.

3/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA not ready

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I.: (\$

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

Ala
veh in
Kennyth
03/11/20

02/11/2020

Owner: ZHUO WEIXIONG

NOT Authorised
C/Ring @
Puhong After Paint
6 days

ESTIMATE TO REPAIR MERCEDES C180 - SJZ1372P

- 1pc rear boot cover
- 2pcs rear boot cover hinge @\$225.00
- 1pc rear boot cover MERCEDES logo
- 1pc rear boot cover outer chrome
- 1pc rear boot cover inner rubber
- 1pc rear boot cover inner lock
- 1pc rear boot cover inner garnish
- 1pc rear boot cover inner trim
- 2pcs rear taillamp @\$680.00
- 1pc rear taillamp RH panel
- 2pcs rear taillamp garnish @\$185.00
- 8pcs rear taillamp garnish clip @\$8.00
- 1pc rear bumper
- 1pc rear bumper centre chrome
- 1pc rear bumper centre garnish
- 2pcs rear bumper side chrome @122.00
- 2pcs rear bumper side garnish @\$165.00
- 2pcs rear bumper side retainer @\$138.00
- 1pc rear bumper reinforcement
- 1pc rear bumper lower garnish
- 2pcs rear bumper lower bracket @\$16.00
- 1pc rear end panel
- 1pc rear end panel inner garnish
- 1pc rear end panel sensor
- 1pc rear fender RH inner trim

Ala	\$ 1,850.00	✓
olsa	nls R \$ 450.00	✗
	n \$ 95.00	✓
	nd \$ 230.00	✓
Dir/Ala	\$ 285.00	50% in
	nd \$ 385.00	✓
	sn \$ 290.00	X
	sn \$ 390.00	X
ols Ala	nls wt \$ 1,360.00	✓
	\$ 385.00	?
ols dir	\$ 370.00	✗
	n \$ 64.00	✓
	R \$ 1,250.00	✓
	cm \$ 164.00	✓
	cm \$ 195.00	✓
	n \$ 244.00	✓
	\$ 330.00	?
	Dir \$ 276.00	✓
	R \$ 757.00	✓
	sn \$ 158.00	X
	Dir \$ 32.00	✓
	\$ 1,205.00	?
	Dir \$ 290.00	✓
	\$ 350.00	?
	\$ 780.00	?

less 10%

\$ 12,185.00
\$ 1,218.50
\$ 10,966.50

- 1set rear parking sensor (system 4)
- 1set rear number plate & casing

nd	s.nett \$ 380.00	✓
sn	s.nett \$ 50.00	X

wiring \$ 180.00
tuffkote \$ 120.00
spray painting \$ 1,500.00
labour charges \$ 1,500.00
Total \$ 14,696.50

2ol
6ol
88ol
75ol
\$ 14,696.50

