



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2007868
INV Date 23/11/2020
Reference CS/SMO20012141/Usd3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SKW 4745G
Insured Veh. YP 7496B
Claim No. CMTD2003223/AGC
Policy No.
Accident Date 05/11/2020
Inspection Date 05/11/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20012141/Usd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 23-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 7496B	Veh. Inspected	SKW 4745G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003223/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	05/11/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0319291	Colour	BLUE
Odometer	69993	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/11/2020	Inspection Date	05/11/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
 B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 4745G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED / TORN	1,062.50	1,062.50
1	REAR BUMPER REINFORCEMENT	DENTED	491.80	491.80
2	REAR BUMPER SIDE RETAINERS @\$34.30	NOT NECESSARY	68.60	-
2	REAR BUMPER REFLECTORS @\$54.90	NOT NECESSARY	109.80	-
2	REAR BUMPER SIDE BRACKETS @\$20.50	NOT NECESSARY	41.00	-
2	REAR BUMPER SPLASH SHIELDS @\$62.60	NOT NECESSARY	125.20	-
1	SETS REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	BOOTLID	DENTED / CRACKED	1,026.70	1,026.70
2	BOOTLID HINGES @\$113.80	NOT NECESSARY	227.60	-
2	BOOTLID REFLECTORS @\$303.50	SCRATCHED	607.00	530.00
2	BOOTLID STOPPERS @\$10.50	NOT NECESSARY	21.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	224.10	-
1	SET BOOTLID INNER TRIM CLIPS	NOT NECESSARY	50.00	-
1	BOOTLID WEATHERSTRIPS	TWISTED	130.60	130.60
1	BOOTLID INNER LOCK	SERVICEABLE	164.50	-
1	BOOTLID LOCK STRIKER	NOT NECESSARY	112.90	-
1	BOOTLID REAR LOGO	NECESSARY	65.80	65.80
1	BOOTLID "MAZDA" EMBLEM	NECESSARY	36.00	36.00
1	BOOTLID 3 EMBLEM	NECESSARY	30.50	30.50
1	BOOTLID SKYACTIV EMBLEM	NECESSARY	608.70	62.20
1	BOOTLID HARNESS	NOT NECESSARY	408.60	-
1	REAR KEY TRANSMITTER ANTENNA	NOT NECESSARY	216.00	-
1	REAR KEY TRANSMITTER ANTENNA CORD	NOT NECESSARY	164.90	-
1	SET REAR LICENSE PLATE LAMP	NOT NECESSARY	144.40	-
1	REAR END PANEL	DENTED	395.30	395.30
1	REAR END PANEL TOP GARNISH	TWISTED	266.50	214.50
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	2,221.00	-
1	REAR FLOOR PANEL TOP BOARD	TORN	605.30	425.50
2	TAILLAMPS @\$941.30	O/S CRACKED	1,882.60	915.00

Report Ref No. CS/SMO20012141/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDERS @\$924.00	NOT NECESSARY	1,848.00	-
2	REAR FENDERS INNER TRIMS @\$285.30	NOT NECESSARY	570.60	-
1	REAR EXHAUST	NOT NECESSARY	952.40	-
2	REAR EXHAUST MOUNTINGS @\$45.00	NOT NECESSARY	90.00	-
2	TAILLAMP HOUSING PANELS @\$164.00	NOT NECESSARY	328.00	-
	LESS 20% DISCOUNT		-	-1,087.28
			15,347.90	4,349.12
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR LICENSE PLATE (SN)	SCRATCHED	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
			430.00	290.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO TRANSFER BOOTLID COMPONENTS.		120.00	60.00
	TO DISMANTLE & REPLACING REVERSE CAMERA.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		120.00	60.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,500.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	-		-	-
	-		-	-
	-		-	-
			3,920.00	1,880.00
GRAND TOTAL			19,697.90	6,519.12

Report Ref No. CS/SMO20012141/Usd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00
---	--	--	-----------------

Report Ref No. CS/SMO20012141/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.