

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012142/ATF3Q2

Date: 10/04/2021

REFERENCE

Insured/Claimant: SERAPHINE VOLKANI ISKANDAR

Policy No: 2070111722

Date of Loss: 28/10/2020

Nature of Claim: OD

Claim No: 4111436077SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU154A**

Make & Model: AUDI Q3, 1.4 TFSI (A)

Engine No: CZD896162

Reg. Date: 27/07/2020 (Man. Year: 2020)

Chassis No: WAUZZZF37L1108405

Colour: Silver

Odometer: 3086 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$140,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R17

Rear Tyre Size: 215/65 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,390.00	3,673.68	10,716.32	74.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,352.00	3,602.00	3,750.00	51.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,742.00	7,275.68	14,466.32	66.54
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	20,942.00	6,475.68	14,466.32	69.08
+ GST 7.00/7.00% (S\$)	1,465.94	453.30	1,012.64	69.08
Nett Amount (S\$)	22,407.94	6,928.98	15,478.96	69.08

INSPECTION

Date of Assignment: 05/11/2020

Date Inspected: 05/11/2020

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,045.00 FS	*1,634.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT -LH	Not Necessary	58.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	215.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE -LH	Not Necessary	109.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE CLOSING ELEMENT	Not Necessary	188.00 FS	*- FS
6	1		*FRONT SPOILER	Cut	379.00 FS	*303.20 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	151.00 FS	*- FS
8	1		*RADIATOR GRILLE	Not Necessary	1,417.00 FS	*- FS
9	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	241.00 FS	*- FS
10	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
11	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	38.00 FS	*- FS
13	1		*FRONT FENDER -LH	Dented	1,271.00 FS	*1,016.80 FS
14	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
15	1		*FRONT FENDER BRACE -LH	Bent	87.00 FS	*68.96 FS
16	1		*FRONT FENDER BRACKET -LH	Bent	31.00 FS	*24.56 FS
17	1		*FRONT WHEEL HOUSING LINER -LH	Deformed	237.00 FS	*189.20 FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	100.00 FS	*- FS
19	1		*HEADLIGHT MOUNTING -LH	Not Necessary	117.00 FS	*- FS
20	1		*LED HEADLIGHT -LH	Not Necessary	5,526.00 FS	*- FS
21	1		*LIFT CYLINDER -LH	Not Necessary	208.00 FS	*- FS
22	2		*FRONT WHEEL COVER -LH/RH	N/S Cut / O/S Necessary	530.00 FS	*424.00 FS
23	1		*FRONT PARKING AID SENSOR	Not Necessary	242.00 FS	*- FS
24	1		*FRONT ALUMINIUM RIM -LH	Not Necessary	756.00 FS	*- FS
25	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
26	1		*SUNDRIES	Necessary	300.00 FS	*12.16 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **14,390.00** **3,673.68**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM ,TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	400.00	280.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER AND LHS FRONT DOOR	New	3,200.00	1,650.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,352.00	3,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >