

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012143/ATF3Q2

Date: 10/04/2021

REFERENCE

Insured/Claimant:	NIENTIE NARWASTU ADMAJAYA	Policy No:	2070116981	
Date of Loss:	31/10/2020	Nature of Claim:	OD	Claim No: 9836239459SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ620E	Engine No:	DKJ043869
Make & Model:	AUDI A1, 999cc SB 1.0 TFSI (PI) (A)	Chassis No:	WAUZZZGB3LR006221
Reg. Date:	06/08/2020 (Man. Year: 2019)	Odometer:	1968 km
Colour:	Yellow		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,998.80	5,584.16	5,414.64	49.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,902.00	2,542.00	3,360.00	56.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,900.80	8,126.16	8,774.64	51.92
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	16,300.80	7,526.16	8,774.64	53.83
+ GST 7.00/7.00% (S\$)	1,141.06	526.83	614.23	53.83
Nett Amount (S\$)	17,441.86	8,052.99	9,388.87	53.83

INSPECTION

Date of Assignment:	05/11/2020		
Date Inspected:	05/11/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,530.00 FS	*1,224.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	135.00 FS	*- FS
3	1		*FRONT SPOILER	Not Necessary	99.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Missing	208.00 FS	*166.40 FS
5	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	194.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	165.00 FS	*- FS
7	1		*FRONT BUMPER CARRIER	Not Necessary	648.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	116.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	106.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE PROFILE-RH	Not Necessary	35.00 FS	*- FS
11	1		*SIGNAL HORN -RH LOW TONE	Not Necessary	126.00 FS	*- FS
12	1		*SIGNAL HORN RETAINER -RH LOW TONE	Not Necessary	29.00 FS	*- FS
13	1		*FRONT FENDER -RH	Dented	878.00 FS	*702.40 FS
14	1		*FRONT FENDER BRACE-RH	Bent	53.00 FS	*42.24 FS
15	1		*FRONT FENDER BRACKET -OUTER	Not Necessary	36.00 FS	*- FS
16	1		*FRONT FENDER BRACKET -MIDDLE	Not Necessary	13.00 FS	*- FS
17	1		*FRONT FENDER BRACKET -INNER	Not Necessary	57.00 FS	*- FS
18	1		*FRONT FENDER TOP COVER -INNER	Not Necessary	22.00 FS	*- FS
19	1		*WHEEL HOUSING LINER	Not Necessary	177.00 FS	*- FS
20	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	69.00 FS	*- FS
21	1		*LED HEADLIGHT -RH	Cracked	4,240.00 FS	*3,392.00 FS
22	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	749.00 FS	*- FS
23	1		*LED WITH HEAT SINK -RH	Not Necessary	708.00 FS	*- FS
24	1		*HEADLIGHT HOSE-RH	Not Necessary	30.00 FS	*- FS
25	1		*LIFT CYLINDER -RH	Not Necessary	141.00 FS	*- FS
26	1		*BONNET IMPACT PROTECTION -CENTRE	Not Necessary	30.00 FS	*- FS
27	1		*BONNET IMPACT PROTECTION -RH	Not Necessary	30.00 FS	*- FS
28	1		*BONNET IMPACT PROTECTION -LH	Not Necessary	30.00 FS	*- FS
29	1		*SUNDRIES	Necessary	300.00 FS	*12.32 FS
30	1		*FRONT FENDER CLOSING ELEMENT -RH	Bent	44.80 FS	*44.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	10,998.80	5,584.16
--------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER ,BONNET AND RHS FRONT FENDER	New	2,900.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,902.00	2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >