

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012144/KBS3Q2

Date: 28/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900164691
<b>Claimant Vehicle No :</b>	SMQ467T	<b>Insured Vehicle No :</b>	SMP4842Y
Date of Loss:	04/11/2020	Nature of Claim:	TP
		Claim No:	1546006417SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMQ467T</b>		
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Engine No:	3ZRB751125
Reg. Date:	17/06/2016 (Man. Year: 2016)	Chassis No:	ZSU600074613
Colour:	Metallic Pearl White	Odometer:	87881 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,350.16	0.00	6,350.16	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,195.00	855.00	41.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,400.16</b>	<b>1,195.00</b>	<b>7,205.16</b>	<b>85.77</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>900.00</b>		
<b>(\$\$)</b>	8,400.16	900.00	7,500.16	89.29
<b>+ GST 7.00/7.00% (\$\$)</b>	588.01	63.00	525.01	89.29
<b>Nett Amount (\$\$)</b>	<b>8,988.17</b>	<b>963.00</b>	<b>8,025.17</b>	<b>89.29</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	05/11/2020	
Date Inspected:	09/11/2020 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	1,446.30 FL	*- FL
2	1		*FRONT FENDER COWLING LH	Serviceable	522.50 FL	*- FL
3	8		*FRONT FENDER COWLING CLIPS	Not Necessary	26.48 FL	*- FL
4	1		*SIDE MIRROR LH	*Check	1,971.80 FL	*- FL
5	1		*SIDE MIRROR COVER LH	*Check	97.50 FL	*- FL
6	1		*FRONT DOOR LH	Repair	1,881.30 FL	*- FL
7	1		*FRONT DOOR PROTECTOR LH	Serviceable	158.70 FL	*- FL
8	1		*REAR DOOR LH	Repair	1,550.40 FL	*- FL
9	1		*REAR DOOR PROTECTOR LH	Serviceable	141.60 FL	*- FL
10	1		*FRONT WHEEL BEARING LH	*Check	670.30 FL	*- FL
11	1		*SPORT RIM LHF (NPA)	Dented	0.00 FS	*- FS
12	1		*TYRE LHF (NPA)	Serviceable	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,466.88</b>	<b>0.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,116.72	0.00
<b>Total Parts (\$\$)</b>	<b>6,350.16</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	15.00
2	TO CHECK AND READJUST WHEEL ALIGNMENT	New	80.00	60.00
3	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR	New	120.00	0.00
4	TO DISMANTLE ,REPLACE AND REINSTALL UNDERCARRIAGE	New	150.00	0.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
6	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD ,TO KNOCK & REPAIR REAR BUMPER INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	700.00	400.00
7	TO SPRAY FRONT FENDER LH ,FRT DOOR LH ,REAR DOOR LH ,SIDE MIRROR LH ,REAR BUMPER	New	900.00	720.00
Gross Labour Cost (\$\$)			<b>2,050.00</b>	<b>1,195.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >