

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20012145/ATD3E2

Date: 19/04/2021

REFERENCE

Insured/Claimant:	TAN KIAN CHYE	Policy No:	2100494350		
Date of Loss:	01/11/2020	Nature of Claim:	OD	Claim No:	7610764795SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ5881X		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN028124
Reg. Date:	16/12/2016 (Man. Year: 2016)	Chassis No:	WAUZZZF46HA091628
Colour:	White	Odometer:	21302 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$87,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,239.00	9,213.12	10,025.88	52.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,452.00	3,372.00	7,080.00	67.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,691.00	12,585.12	17,105.88	57.61
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	29,091.00	11,985.12	17,105.88	58.80
+ GST 7.00/7.00% (S\$)	2,036.37	838.96	1,197.41	58.80
Nett Amount (S\$)	31,127.37	12,824.08	18,303.29	58.80

INSPECTION

Date of Assignment:	05/11/2020		
Date Inspected:	05/11/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	282.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Necessary	70.00 FS	*55.68 FS
4	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	208.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE -LH	Damaged	62.00 FS	*49.52 FS
7	1		*RADIATOR GRILLE	Not Necessary	1,139.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Deformed	134.00 FS	*106.80 FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	126.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION -LH	Damaged	36.00 FS	*28.48 FS
13	1		*CAUTIN SIGN STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
15	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*- FS
16	2		*LOCK CARRIER BRACKET SUPPORT -LH/RH	Not Necessary	56.00 FS	*- FS
17	1		*HORN -LH HIGH TONE	Not Necessary	124.00 FS	*- FS
18	1		*SPRING SHACKLE -LH	Not Necessary	29.00 FS	*- FS
19	1		*FRONT FENDER -LH	Distorted	758.00 FS	*606.00 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	200.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT -LH	Distorted	49.00 FS	*39.20 FS
22	1		*FRONT FENDER BRACKET -LH	Bent	35.00 FS	*27.60 FS
23	1		*DEFORMATION ELEMENT BRACKET-LH	Not Necessary	49.00 FS	*- FS
24	1		*FRONT FENDER BRACKET -LH INNER	Not Necessary	31.00 FS	*- FS
25	1		*FRONT FENDER BRACE -LH FRONT	Bent	117.00 FS	*93.60 FS
26	1		*WHEEL HOUSING LINER -LH	Deformed	237.00 FS	*189.20 FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
28	1		*WHEEL SPOILER	Deformed	73.00 FS	*57.76 FS
29	1		*WHEEL SPOILER TRIM -LH	Not Necessary	35.00 FS	*- FS
30	1		*STONE CHIP GUARD	Necessary	50.00 FS	*39.92 FS
31	1		*FENDER LEDGE TOP COVER -UPPER	Necessary	31.00 FS	*24.40 FS
32	1		*FENDER LEDGE TOP COVER -LOWER	Deformed	23.00 FS	*17.68 FS
33	1		*BONNET IMPACT PROTECTION -CENTRE	Not Necessary	27.00 FS	*- FS
34	1		*BONNET IMPACT PROTECTION -LH	Not Necessary	28.00 FS	*- FS
35	1		*BONNET IMPACT PROTECTION -RH	Not Necessary	27.00 FS	*- FS
36	1		*LED HEADLIGHT -LH	Cracked	7,693.00 FS	*6,154.40 FS
37	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	739.00 FS	*- FS
38	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	742.00 FS	*- FS
39	1		*HEADLIGHT HOSE -LH	Not Necessary	36.00 FS	*- FS
40	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	40.00 FS	*- FS
41	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	40.00 FS	*- FS
42	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	40.00 FS	*- FS
43	1		*LIFT CYLINDER -LH	Not Necessary	208.00 FS	*- FS
44	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	92.00 FS	*- FS
45	1		*LOCK CARRIER	Not Necessary	1,004.00 FS	*- FS
46	1		*READY MIX COOLANT	Not Necessary	91.00 FS	*- FS
47	1		*RADIATOR AIR GUIDE-LH INNER	Not Necessary	28.00 FS	*- FS
48	1		*RADIATOR AIR GUIDE-LH OUTER	Not Necessary	12.00 FS	*- FS
49	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	18.00 FS	*- FS
50	1		*FRONT ALUMINIUM RIM -LH	Not Necessary	589.00 FS	*- FS
51	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
52	1		*SUNDRIES	Necessary	300.00 FS	*34.08 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,239.00 9,213.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM .TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	350.00	280.00
4	TO REMOVE AND REINSTALL AIRCON CONDENSER,CHARGES AIR COOLER AND RADIATOR .CHECK ELECTRICAL FANS AND CONTROL UNIT,PRESSURISE COOLING SYSTEM .TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER ,AND LHS HEADLIGHT .TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
6	TO RESPRAY FRONT BUMPER ,BONNET ,LHS FRONT FENDER AND LHS FRONT DOOR	New	3,600.00	1,650.00
7	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			10,452.00	3,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >