

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20012146/EQF3E2

Date: 19/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100203385
Claimant Vehicle No : SFZ8736A	Insured Vehicle No :	SJW7237Z
Date of Loss: 05/11/2020	Nature of Claim:	TP Claim No: 1453599230SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFZ8736A		
Make & Model:	BMW 218i, 1.5 ACTIVE TOURER D/AB LED DSC	Engine No:	30539328B38A15A
Reg. Date:	29/09/2015 (Man. Year: 2015)	Chassis No:	WBA2A32040V458838
Colour:	Black	Odometer:	110592 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	05/11/2020		
Date Inspected:	06/11/2020	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1		*FRT BUMPER	Broken	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER BRACKET	Broken	0.00 F	*- F
6	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT UPPER	Bent	0.00 F	*- F
8	1		*FRT BUMPER BEAM LOWER	Bent	0.00 F	*- F
9	1		*FRT BUMPER SPONGE	Broken	0.00 F	*- F
10	1		*FRT BUMPER TOW EYE COVER	Cut	0.00 F	*- F
11	1		*FRT BUMPER GRILLE LOWER	Broken	0.00 F	*- F
12	2		*FRT BUMPER SENSOR	Broken	0.00 F	*- F
13	1		*FRT RH BUMPER FOG LAMP COVER	Missing	0.00 F	*- F
14	1		*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*- F
15	2		*FRT GRILLE	Broken	0.00 F	*- F
16	1		*FRT EMBLEM	Necessary	0.00 F	*- F
17	1		*FRT SUPPORT PANEL U BAR	Bent	0.00 F	*- F
18	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
19	1		*AIR CON CONDENSER	Dented	0.00 F	*- F
20	1		*RADIATOR	* Check	0.00 F	*- F
21	1		*RADIATOR FAN ASSY	* Check	0.00 F	*- F
22	1		*AIR DUCT	Broken	0.00 F	*- F
23	1		*FRONT RH REINFORCEMENT BRACKET	Bent	0.00 F	*- F
24	1		*WIPER WASHER TANK	Crushed	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >