

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : **Toyota Hiace Commuter 2.8GL AT**
 Registraion No : **PC 7838 Z**
 Chassis No: **GDH2232001106**
 Year of Manufacturing: **2018**

S/No	Qty	Items	Unit Price	Amount
1	1	Tailgate / <i>huc</i>		\$ 2287.30 - 2150.7
2	2	Tailgate Hinge X		\$ 88.50 -
3	1	Tailgate Weatherstrip X		\$ 474.90 -
4	1	Tailgate Inner Trim Board /		\$ 1280.50 - 425.1
5	1	Tailgate Lock /		\$ 376.60 - ✓
6	1	Tailgate Lock Actuator X		\$ - -
7	1	Tailgate Logo /		\$ 82.20 - 68
8	1	Tailgate Emblem - Toyota /		\$ 88.90 - 62
9	1	Tailgate Emblem - Hiace /		\$ 88.90 - 62
10	1	Tailgate Emblem - G.L /		\$ 78.90 - 65
11	1	Tailgate Windscreen Moulding /		\$ 96.30 - ✓
12	1	Rear Bumper /		\$ 530.90 - ✓
13	2	Rear Bumper Retainer /		\$ 68.60 - ✓
14	4	Rear Bumper Bracket X		\$ 19.70 -
15	1	End Panel Inner X <i>repair</i>		\$ 1104.70 -
16	1	End Panel Outer /		\$ 559.90 - ✓
17	1	Rear Floor Panel X		\$ 2780.50 -

\$	-	4465.1
----	---	--------

-25%	\$	-
------	----	---

Total for spare parts	\$	-	3348.82
-----------------------	----	---	---------

Special Nett

1	1	Rear Bumper Clip set /	\$	50.00	\$	50.00	30
2	1	Rear Bumper Reverse Sensor /	\$	350.00	\$	350.00	200
3	1	Tailgate Sticker - 70km/h /	\$	35.00	\$	35.00	10
4	1	Tailgate Emblem - JESUS /	\$	65.00	\$	65.00	10

Total for SP	\$	500.00	250
--------------	----	--------	-----

Sub-Total for Parts :	\$	500.00
-----------------------	----	--------

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	900.00 600
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,200.00 600
3		To check wiring system to facilitate repair and refit the same	\$	60.00 80 X NN
4		Apply rust proofing on the adjacent panels	\$	80.00
5		To supply under coating / putty on parts replaced	\$	50.00 } 60
6		To perform water seepage test after repair	\$	80.00 X NN
7		Remove and refit tailgate mechanism	\$	180.00 } 60
8		Remove and refir rear end panel lining and garnish to facilitate repair	\$	80.00
9		Remove and refit rear reverse sensor	\$	80.00 40
10		Remove and refit rear windscreen	\$	180.00 100
TOTAL AMOUNT :			\$	2,890.00 1460
OVERALL COST:			\$	3,390.00

5 Days.
Lump sum repair
After repair photos.
Gmo Repair.

5058.82

-20%: 4050

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Authorised by Repairer
Signature: _____
Date: _____