

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20010439/GVD3E2-1
Date: 23/11/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001439765
Claimant Vehicle No : GBJ6199U	Insured Vehicle No :	GY7678J
Date of Loss: 28/09/2020	Nature of Claim:	TP Claim No: 248135

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ6199U	Engine No:	HR16148088D
Make & Model:	NISSAN NV200, 1.6 VANETTE DX (A)	Chassis No:	VM20135784
Reg. Date:	20/06/2019 (Man. Year: 2019)	Odometer:	22926 km
Colour:	Silver		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,892.77	4,696.74	2,196.03	31.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,760.00	1,770.00	50.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,422.77	6,456.74	3,966.03	38.05
Approved Total (Overridden) (S\$)		5,800.00		
Nett Amount (S\$)	10,422.77	5,800.00	4,622.77	44.35

INSPECTION

Date of Assignment:	29/09/2020		
Date Inspected:	30/09/2020	Inspected At:	Mhl Automobiles Services (HQ) BLK 3006 UBI ROAD 1, #01-360 Singapore 408700
Estimated Period of Repair:	6.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Nov 2020)	
Parts:	N/A	NISSAN NV200 1.6 VANETTE DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ6199U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE ASSY	Dented / Bent / Distorted	2,025.90 FL	*1,724.60 FL
2	1		*TAIL GATE INNER LOCK ASSY	Distorted / Bent	99.00 FL	*99.00 FL
3	1		*TAIL GATE NISSAN LOGO	Necessary	66.40 FL	*66.40 FL
4	1		*TAIL GATE NV200 EMBLEM	Necessary	163.50 FL	*75.00 FL
5	1		*TAIL GATE VANETTE EMBLEM	Necessary	85.10 FL	*75.00 FL
6	1		*TAIL GATE INNER TRIM BOARD	Dented / Cover Torn	212.50 FL	*189.00 FL
7	1		*TAIL GATE WEATHERSTRIP	Dented / Channel Deformed	83.90 FL	*63.70 FL
8	1		*REAR BUMPER	Buckled / Deformed	650.50 FL	*437.90 FL
9	1		*REAR BUMPER INNER FOAM	Squashed / Cut	133.80 FL	*94.00 FL
10	2		*REAR BUMPER SIDE RETAINER	Serviceable	70.40 FL	*- FL
11	1		*REAR END PANEL OUTER	Dented / Bent / Distorted	246.20 FL	*189.00 FL
12	1		*REAR END PANEL INNER	To Repair / Repaint	880.40 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Bent / Deformed	85.00 FL	*69.50 FL
14	1		*FRONT BUMPER	Dented / Scraped	682.20 FL	*536.10 FL
15	2		*FRONT BUMPER SIDE RETAINER	Serviceable	64.80 FL	*- FL
16	1		*FRONT BUMPER INNER FOAM	Cracked	280.70 FL	*265.10 FL
17	1		*FRONT BUMPER REINFORCEMENT	Dented / Bent	591.90 FL	*591.90 FL
18	1		*TOW-EYE COVER	Dented / Scraped	18.20 FL	*18.20 FL
19	1		*FRONT SUPPORT PANEL	To Repair / Repaint	295.70 FL	*- FL
20	1		*FRONT GRILLE C/LOGO	Scraped / Bent	299.20 FL	*299.20 FL
21	1		*TAIL GATE 70 KM/H STICKER	Necessary	15.00 FS	*10.00 FS
22	10		*REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
23	1		*SET REVERSE SENSOR	Casing squashed / Shorted	280.00 FS	*200.00 FS
24	1		*TAIL GATE INNER TRIM BOARD CLIP (19PCS)	Necessary	66.50 FS	*30.00 FS
25	5		*REAR END PANEL TOP GARNISH CLIP	Necessary	22.50 FS	*22.50 FS
26	1		*FRONT GRILLE CLIP (6PCS)	Necessary	27.00 FS	*20.00 FS
27	10		*FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
28	1		*SET FRONT NUMBER PLATE	Broken / Cracked	70.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,596.30	5,176.10
- List Item Discount on L Items 10.00/10.00% (S\$)	703.53	479.36
Total Parts (S\$)	6,892.77	4,696.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	40.00	30.00
2	TO APPLY ANTI-RUST UNDERCOAT (NPA)	New	0.00	0.00
3	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS	New	1,500.00	800.00
4	SPRAY PAINTING CHARGES TO PAINT THE TAIL GATE, REAR END PANEL-OUTER, REAR END PANEL-INNER, LH REAR FENDER (SCRAPED), FRONT GRILLE, FRONT SUPPORT PANEL AND NECESSARY AREAS	New	1,500.00	600.00
5	TO REMOVE TAIL GATE WIRING HARNESS, INNER FITTINGS AND ATTACHMENTS TO NEW TAIL GATE	New	90.00	60.00
6	TO REMOVE, TRANSFER AND INSTALL REAR WINDSCREEN	New	150.00	120.00
7	TO SUPPLY AND INSTALL TAIL GATE COMPANY LOGO ARTWORK AND INFORMATION STICKER	New	250.00	150.00
Gross Labour Cost (\$\$)			3,530.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >