

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20009736/GTD3E2-1
Date: 04/12/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant Vehicle No : SFN1811A**Insured Vehicle No :** SLU5134L

Date of Loss: 11/09/2020

Nature of Claim: TP

Claim No: 628525

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFN1811A**

Make & Model: HONDA ACCORD, 2.4 L (A)

Engine No: K24Z21957460

Reg. Date: 29/07/2008 (Man. Year: 2008)

Chassis No: MRHCP26308P020507

Colour: Beige

Odometer: 181142 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size:

225/50 R17

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,804.48	3,487.60	2,316.88	39.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,045.00	1,990.00	2,055.00	50.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,849.48	5,477.60	4,371.88	44.39
Approved Total (Overridden) (S\$)		4,400.00		
Nett Amount (S\$)	9,849.48	4,400.00	5,449.48	55.33

INSPECTION

Date of Assignment: 11/09/2020

Date Inspected: 11/09/2020 Inspected At:

Hua Kian Motor Workshop (HQ)
1 Kaki Bukit Ave 6, #02-37 Autobay @
Kakibukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2020)
Parts:	143	HONDA ACCORD 2.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFN1811A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Squashed / Torn	707.70 FL	*707.70 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Broken	43.00 FL	*43.00 FL
3	10		*REAR BUMPER CLIP	Necessary	55.00 FL	*30.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent / Distorted	257.10 FL	*257.10 FL
5	1		*REAR END PANEL	Dented / Bent / Distorted	422.40 FL	*317.40 FL
6	1		*REAR END PANEL GARNISH	Squashed / Bent	94.00 FL	*94.00 FL
7	4		*REAR END PANEL GARNISH CLIP	Necessary	23.20 FL	*23.20 FL
8	1		*SPARE TYRE PANEL	Crumpled / Distorted	1,238.80 FL	*837.50 FL
9	1		*SPARE TYRE PANEL BOARD	Reuse	232.00 FL	*- FL
10	1		*REAR BOOT LID	Repair	728.20 FL	*- FL
11	1		*REAR BOOT LID LOCK ASSY	Bent / Distorted	189.20 FL	*189.20 FL
12	1		*REAR BOOT LID LOWER CATCH	Repair	19.40 FL	*- FL
13	1		*REAR BOOT WEATHERSTRIP	Reuse	56.90 FL	*- FL
14	2		*REAR BOOT LID HINGE	Repair	102.40 FL	*- FL
15	1		*REAR BOOT LID HONDA LOGO	Necessary	21.80 FL	*21.80 FL
16	1		*REAR BOOT LID 2.4 I-VTEC EMBLEM	Necessary	50.20 FL	*33.20 FL
17	1		*REAR BOOT LID ACCORD EMBLEM	Necessary	24.00 FL	*24.00 FL
18	1		*RH TAILLAMP ASSY	Side bracket bent	283.50 FL	*283.50 FL
19	1		*RH TAILLAMP LOWER BRACKET	Bent / Distorted	11.60 FL	*11.60 FL
20	1		*RH REAR FENDER	Repair	908.90 FL	*- FL
21	1		*EXHAUST SILENCER	Bent / Torn	998.80 FL	*998.80 FL
22	1		*SET REAR PARKING SENSORS	Broken	280.00 FS	*200.00 FS
23	1		*SPARE TYRE PANEL SOUND PROOFING PAD	Necessary	200.00 FS	*150.00 FS
24	1		*END PANEL JOINT RUBBERISED SEALER	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,098.10	4,262.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,293.62	774.40
Total Parts (\$\$)	5,804.48	3,487.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING CONDITION AND REPAIR WHERE NEEDED	New	45.00	30.00
2	TO INSTALL REAR PARKING SENSORS AND CHECK SENSING FUNCTIONS	New	80.00	40.00
3	TO APPLY ANTI-RUST UNDERCOATING	New	200.00	60.00
4	TO REMOVE AND TRANSFER REAR BOOT LID WIRE HARNESSSES, FITTINGS AND ATTACHMENTS TO NEW BOOT LID	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE AFFECTED PARTS / AREAS	New	2,100.00	800.00
6	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS / AREAS - REAR BUMPER, REAR RH FENDER, REAR END PANEL, SPARE TYRE PANEL, REAR BOOT LID, REAR BOOT LID HINGES, ETC	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			4,045.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >