



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 8089J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FORK ASSY	SERVICEABLE	980.00	-
1	FORK UNDER BRACKET	SERVICEABLE	255.00	-
1	HEADLAMP	DAMAGED	550.00	485.00
1	N/S SIDE MIRROR	DAMAGED	120.00	120.00
1	HANDLE-BAR	DAMAGED	185.00	135.00
1	SET HANDLE-BAR BALANCER	DAMAGED	80.00	80.00
1	N/S BRAKE LEVER	DAMAGED	52.00	52.00
1	FRONT N/S SIGNAL	DAMAGED	95.00	95.00
1	RADIATOR	SERVICEABLE	525.00	-
1	RADIATOR GRILLE	SERVICEABLE	155.00	-
1	N/S FOOTSTEP PANEL	DAMAGED	120.00	120.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	880.00	-
1	EXHAUST PROTECTOR	DAMAGED	78.00	78.00
1	REAR SIGNAL	SERVICEABLE	80.00	-
1	REAR N/S FOOTREST	SERVICEABLE	65.00	-
1	DROVE BELT COVER	DAMAGED	340.00	340.00
1	MAIN STAND	DAMAGED	145.00	145.00
1	SIDE STAND	DAMAGED	95.00	40.00
1	SET FAIRING COVER	DAMAGED	1,250.00	1,050.00
	LESS 10% DISCOUNT		-605.00	-274.00
			5,445.00	2,466.00
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	SERVICEABLE	28.00	-
1	REAR BOX (SN)	DAMAGED	350.00	280.00
1	REAR BOX BRACKET (SN)	SERVICEABLE	150.00	-
1	DELIVERY BAG (SN)	SERVICEABLE	550.00	-
			1,078.00	280.00
<u>LABOUR</u>				
	TO PROVIDE TOWING SERVICE.		50.00	35.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY.		480.00	200.00
	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION.	NOT NECESSARY	350.00	-
			960.00	235.00
GRAND TOTAL			7,483.00	2,981.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS3/AIG20010668/Gvd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.