

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012158/DTF3E2

Date: 30/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00055962005
Claimant Vehicle No :	SKJ4580H	Insured Vehicle No :	GY7871S
Date of Loss:	04/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204229/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ4580H	Engine No:	4GR0370224
Make & Model:	TOYOTA MARK X, 2.5 (A)	Chassis No:	GRX1203042384
Reg. Date:	17/09/2007 (Man. Year: 2007)	Odometer:	197469 km
Colour:	Blue		
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,970.16	10,499.48	25,470.68	70.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,000.00	2,660.00	5,340.00	66.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,970.16	13,159.48	30,810.68	70.07
Approved Total (Overridden) (S\$)		10,500.00		
(S\$)	43,970.16	10,500.00	33,470.16	76.12
+ GST 7.00/7.00% (S\$)	3,077.91	735.00	2,342.91	76.12
Nett Amount (S\$)	47,048.07	11,235.00	35,813.07	76.12

INSPECTION

Date of Assignment: 06/11/2020
 Date Inspected: 06/11/2020 Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08
 AMK AutoPoint
 Singapore 568047

Estimated Period of Repair: 9.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
Parts:	143	TOYOTA MARK X 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ4580H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,339.78 FL	*1,285.30 FL
2	2		*BONNET HINGE	Not Necessary	111.16 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	421.74 FL	*- FL
4	1		*HEAD LAMP PANEL LH	Not Necessary	255.01 FL	*- FL
5	1		*HEAD LAMP ECU LH	Not Necessary	997.04 FL	*- FL
6	1		*FRONT GRILLE	Not Necessary	658.46 FL	*- FL
7	1		*FRONT BUMPER	Dented	530.50 FL	*530.50 FL
8	2		*FRONT BUMPER SIDE RETAINER LH / RH	Serviceable	174.80 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	98.20 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Not Necessary	195.97 FL	*- FL
11	1		*FRONT FENDER LH	Buckled	861.45 FL	*695.00 FL
12	1		*FRONT FENDER INNER SHIELD LH	Deformed	315.76 FL	*260.45 FL
13	1		*FRONT WHEEL HOUSING LH	Repair	893.10 FL	*- FL
14	1		*FRONT WHEEL BEARING LH	Damaged	492.65 FL	*492.65 FL
15	1		*FRONT WHEEL BEARING HUB LH	Not Necessary	499.82 FL	*- FL
16	1		*FRONT LOWER ARM LH	Distorted	575.40 FL	*575.40 FL
17	1		*FRONT KNUCKLE ARM LH	Distorted	581.94 FL	*581.94 FL
18	1		*FRONT ABSORBER MOUNTING LH	Not Necessary	252.10 FL	*- FL
19	1		*FRONT ABSORBER LINK LH	Not Necessary	230.48 FL	*- FL
20	1		*FRONT TIE ROD LH	Not Necessary	297.20 FL	*- FL
21	1		*FRONT TIE ROD END LH	Not Necessary	172.10 FL	*- FL
22	1		*FRONT STABILIZER BAR	Not Necessary	456.17 FL	*- FL
23	1		*FRONT STABILIZER LINK LH	Not Necessary	319.29 FL	*- FL
24	1		*STEERING RACK & PINION ASSY	Not Necessary	6,493.02 FL	*- FL
25	1		*FRONT DOOR LH	Dented	1,580.74 FL	*1,345.00 FL
26	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	319.70 FL	*- FL
27	1		*FRONT DOOR CHROME MOULDING LH	Not Necessary	197.72 FL	*- FL
28	1		*FRONT DOOR BLACK PLASTIC MOULDING LH	Not Necessary	151.66 FL	*- FL
29	2		*FRONT DOOR HINGE LH	Not Necessary	174.02 FL	*- FL
30	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	286.34 FL	*- FL
31	1		*FRONT DOOR HANDLE LH	Not Necessary	266.78 FL	*- FL
32	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	1,228.10 FL	*- FL
33	1		*REAR DOOR LH	Dented	1,326.50 FL	*1,211.40 FL
34	1		*REAR DOOR WINDOW MOULDING LH	Not Necessary	207.10 FL	*- FL
35	1		*REAR DOOR CHROME MOULDING LH	Not Necessary	207.38 FL	*- FL
36	1		*REAR DOOR BLACK PLASTIC MOULDING LH	Not Necessary	167.34 FL	*- FL
37	2		*REAR DOOR HINGE LH	Not Necessary	174.20 FL	*- FL
38	1		*REAR DOOR WEATHER STRIP LH	Not Necessary	268.17 FL	*- FL
39	1		*REAR DOOR HANDLE LH	Not Necessary	168.47 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	1,009.80 FL	*- FL
41	1		*SIDE MIRROR ASSY LH	Broken	1,209.20 FL	*1,209.20 FL
42	1		*REAR FENDER LH	Dented	1,094.10 FL	*1,094.10 FL
43	1		*REAR FENDER INNER SHIELD LH	Not Necessary	144.73 FL	*- FL
44	1		*REAR FENDER INNER TRIM LH	Not Necessary	774.10 FL	*- FL
45	1		*REAR BUMPER	Not Necessary	596.30 FL	*- FL
46	2		*REAR BUMPER SIDE RETAINER LH / RH	Not Necessary	165.62 FL	*- FL
47	1		*REAR WHEEL HOUSING LH	Not Necessary	1,369.00 FL	*- FL
48	1		*REAR WHEEL BEARING LH	Not Necessary	456.00 FL	*- FL
49	1		*REAR WHEEL BEARING HUB LH	Not Necessary	489.00 FL	*- FL
50	1		*REAR LOWER ARM LH	Not Necessary	401.95 FL	*- FL
51	1		*REAR KNUCKLE ARM LH	Not Necessary	967.90 FL	*- FL
52	1		*REAR ABSORBER LH	Not Necessary	390.90 FL	*- FL
53	1		*REAR ABSORBER MOUNTING LH	Not Necessary	424.60 FL	*- FL
54	1		*REAR ABSORBER LINK LH	Not Necessary	333.10 FL	*- FL
55	1		*ENGINE UNDERCOVER	Torn	679.89 FL	*191.70 FL
56	1		*LED FOG LAMP	Not Necessary	1,500.00 FS	*- FS
57	1		*SPORT RIM	N/S Front Cut / Dented	3,000.00 FS	*500.00 FS
58	1		*TYRE (\$250.00) (50%)	N/S Front Punctured	500.00 FS	*125.00 FS
59	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
61	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
63	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
64	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
65	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
66	1		*REAR DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
67	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
68	1		*HEAD LAMP LH	Scratched / Mtg Broken	2,500.00 FS	*1,800.00 FS
69	1		*ABSORBER LH	Distorted	2,000.00 FS	*900.00 FS
70	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
71	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
72	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	44,583.55	12,867.64
- List Item Discount on L Items 25.00/25.00% (\$\$)	8,613.39	2,368.16
Total Parts (\$\$)	35,970.16	10,499.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	500.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANEL (FRONT)	New	1,400.00	1,200.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	1,400.00	1,000.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR) (Repeated)	New	1,400.00	0.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR) (Repeated)	New	1,400.00	0.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR FRONT UNDER CARRIAGE TO FACILITATE REPAIRS	New	300.00	150.00
8	TO RNR REAR UNDER CARRIAGE TO FACILITATE REPAIRS	New	300.00	0.00
9	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
10	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
11	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
12	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
13	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS, RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			8,000.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >