

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20012160/KSD3E2

Date: 24/12/2020

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 0999993880

Date of Loss: 01/11/2020

Nature of Claim: OD

Claim No: 5340413247SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG6355B	Engine No:	65195034218196
Make & Model:	MERCEDES-BENZ VITO 114, 2.1 CDI PANEL VAN LONG ABS 5DR (A)	Chassis No:	WDF44760323339042
Reg. Date:	18/09/2017 (Man. Year: 2017)	Odometer:	81150 km
Colour:	White/Red		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	S\$47,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,693.10	3,749.80	943.30	20.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,660.00	1,720.00	50.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,073.10	5,409.80	2,663.30	32.99
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	6,673.10	4,009.80	2,663.30	39.91
+ GST 7.00/7.00% (S\$)	467.12	280.69	186.43	39.91
Nett Amount (S\$)	7,140.22	4,290.49	2,849.73	39.91

INSPECTION

Date of Assignment: 06/11/2020

Date Inspected: 06/11/2020 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (WCP)	Bent	1,450.00 F	*1,450.00 F
2	1		*TAILGATE WEATHERSTRIP (WCP)	Serviceable	180.00 F	*- F
3	1		*TAILGATE CENTRE LOGO (WCP)	Necessary	48.00 F	*48.00 F
4	1		*TAILGATE VITO EMBLEM (WCP)	Necessary	52.00 F	*52.00 F
5	1		*TAILGATE 114 CDI EMBLEM (WCP)	Necessary	62.00 F	*62.00 F
6	1		*TAILGATE C & C EMBLEM (WCP)	Necessary	38.00 F	*38.00 F
7	15		*TAILGATE TRIMBOARD CLIPS (WCP)	Necessary	107.25 FS	*30.00 FS
8	1		*TAILLAMP ASSY - RH (WCP)	Cracked	550.00 F	*550.00 F
9	1		*TAILLAMP LOWER GARNISH - RH (WCP)	Buckled	98.00 F	*98.00 F
10	1		*REAR BUMPER (WCP)	Buckled	980.00 F	*980.00 F
11	1		*REAR BUMPER REINFORCEMENT (WCP)	Repair	135.00 F	*- F
12	6		*REAR BUMPER SENSOR SEALS (WCP)	Not Necessary	48.00 F	*- F
13	1		*REAR BUMPER CLIPS (15PCS)(WCP)	Necessary	90.75 FS	*50.00 FS
14	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
15	1		*70KM/H STICKER	Necessary	25.00 FS	*12.00 FS
16	1		*6 PAX STICKER	Necessary	25.00 FS	*12.00 FS
17	1		*SET REAR BUMPER SENSOR	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,329.00	3,422.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	364.10	327.80
Total Parts (\$\$)	4,693.10	3,749.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR BUMPER SENSOR	New	100.00	60.00
2	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE	New	150.00	60.00
3	TO CHECK AND RECTIFY WIRING SYSYEM AND FOCUS OF LIGHTING	New	80.00	20.00
4	TO PANEL BEAT AND STRAIGHTEN REAR CHASSIS FRAME, REAR FLOORBOARD PANEL, REAR BUMPER BRACKET INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	350.00
5	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS	New	800.00	200.00
6	TO SUPPLY ARTWORK AND SPRAY BARCODE ON TAILGATE	New	1,100.00	850.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
Gross Labour Cost (\$\$)			3,380.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >