

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20012164/R1GA3Q2

**Date:** 06/01/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0002258
<b>Claimant Vehicle No :</b>	SLU4852D	<b>Insured Vehicle No :</b>	SLC2159E
Date of Loss:	30/10/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0002250

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU4852D	Engine No:	32635101B38A15A
Make & Model:	BMW 216I, 1.5 D GT LED (A)	Chassis No:	WBA2D920605E91546
Reg. Date:	01/12/2017 (Man. Year: 2017)	Odometer:	40820 km
Colour:	Blue		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,056.86	2,831.05	3,225.81	53.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,040.00	3,020.00	2,020.00	40.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>11,096.86</b>	<b>5,851.05</b>	<b>5,245.81</b>	<b>47.27</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	776.78	409.57	367.21	47.27
<b>Nett Amount (\$\$)</b>	<b>11,873.64</b>	<b>6,260.62</b>	<b>5,613.02</b>	<b>47.27</b>
<b>+ Loss of Use (8.0 x S\$60.00/day) (\$\$)</b>		480.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>6,742.62</b>		

### INSPECTION

Date of Assignment:	03/11/2020	
Date Inspected:	18/11/2020 Inspected At:	Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre Singapore 159942
Estimated Period of Repair:	6.0 days	

---

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2020)
<b>Parts:</b>	M1-MPV	BMW 216I 1.5 D GT LED (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLU4852D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE PANEL	Bent	1,287.81 FS	*1,287.81 FS
2	1		*TAILGATE RUBBER BEADING	Serviceable	162.62 FS	*- FS
3	1		*REAR WINDSCREEN GLASS	Not Necessary	612.23 FS	*- FS
4	1		*REAR WINDSCREEN GLASS SEALANT (2 PCS)	Necessary	279.95 FS	*279.95 FS
5	1		*REAR BUMPER	Cracked	1,112.35 FS	*1,112.35 FS
6	1		*REAR BUMPER INNER GUIDE LH	Serviceable	69.36 FS	*- FS
7	1		*REAR BUMPER INNER GUIDE RH	Serviceable	69.36 FS	*- FS
8	1		*REAR BUMPER SIDE GUIDE LH	Serviceable	69.36 FS	*- FS
9	1		*REAR BUMPER SIDE GUIDE RH	Serviceable	69.36 FS	*- FS
10	1		*REAR BUMPER REINFORCEMENT	Serviceable	489.87 FS	*- FS
11	1		*SET MOUNTS PDC SENSOR REAR	Serviceable	68.62 FS	*- FS
12	1		*TAILGATE LOGO EMBLEM	Necessary	80.94 FS	*80.94 FS
13	1		*SUPPORT	Serviceable	51.49 FS	*- FS
14	1		*REAR BUMPER TOWING COVER	Serviceable	48.67 FS	*- FS
15	1		*REAR END PANEL	Repair	379.85 FS	*- FS
16	1		*INTERIOR TAIL TRIM	Serviceable	298.45 FS	*- FS
17	2		*REAR BUMPER REVERSE SENSOR	Serviceable	836.57 FS	*- FS
18	1		*REAR NUMBER PLATE	Bent	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **6,056.86** **2,831.05**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE REAR BUMPER ,TAILGATE PANEL,REAR END PANEL AND ALL AFFECTED AREAS	New	1,800.00	1,050.00
2	TO RESPRAY AND PUTTY TAILGATE PANEL ,REAR BUMPER ,REAR END PANEL AND ALL AFFECTED AREAS	New	1,500.00	1,050.00
3	TO CARRY OUT BODY CAVITY PRESERVATION	New	180.00	90.00
4	TO CONDUCT ECU PROGRAMMING CHECK AND TO CLEAR FAULT CODES	New	380.00	300.00
5	TO TRANSFER AND REFIX REAR TAILGATE FITTINGS TRIM AND MECHANICAL COMPONENTS	New	300.00	150.00
6	TO REMOVE AND REAR WINDSCREEN GLASS ,CONDUCT WATER TEST LEAKS	New	380.00	300.00
7	TO REMOVE AND REINSTALL REAR SENSORS AND CONDUCT DISTANCE SETTINGS	New	150.00	80.00
8	TO SUPPLY AND INSTALL REAR WINDSCREEN GLASS SOLAR FILM	New	350.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,040.00</b>	<b>3,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >