

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20012165/AQF3Q2**Date:** 15/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00062802000

Claimant Vehicle No : GX9254R **Insured Vehicle No :** GBJ7824S

Date of Loss: 04/11/2020 Nature of Claim: TP Claim No: SNM20D204231/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GX9254R**

Make & Model: NISSAN URVAN, 3.0 5MT (A) Engine No: ZD30044387

Reg. Date: 30/10/2004 (Man. Year: 2004) Chassis No: JN1MG4E25Z0712032

Colour: Silver Odometer: 589393 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,178.60	5,636.09	5,542.51	49.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	2,950.00	1,620.00	35.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,748.60	8,586.09	7,162.51	45.48
Approved Total (Overridden) (\$\$)		6,800.00		
Nett Amount (\$\$)	15,748.60	6,800.00	8,948.60	56.82

INSPECTION

Date of Assignment: 06/11/2020

Date Inspected: 06/11/2020 Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Sep 2022)	
Parts:	N/A	NISSAN URVAN 3.0 5MT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX9254R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR BUMPER SIDE BRACKET LH & RH	Necessary	126.00 FL	*70.00 FL
2	2		*REAR BUMPER CENTER STEP PANEL	Dented	283.40 FL	*283.40 FL
3	1		*REAR TAILGATE	Distorted	2,101.00 FL	*2,101.00 FL
4	2		*REAR TAILGATE DAMPER LH & RH	Not Necessary	600.00 FL	*- FL
5	2		*REAR TAILGATE HINGE LH & RH	Not Necessary	276.40 FL	*- FL
6	1		*REAR TAILGATE INNER BOARD	Torn	380.00 FL	*165.00 FL
7	1		*REAR TAILGATE LOCK STRICKER	Not Necessary	53.00 FL	*- FL
8	1		*REAR TAILGATE MECHANISM LOCK	Jammed	340.00 FL	*340.00 FL
9	1		*REAR TAILGATE WEATHERSTRIP	Cut	180.00 FL	*180.00 FL
10	2		*REAR TAILGATE RUBBER STOPPER LH & RH	Not Necessary	185.40 FL	*- FL
11	1		*REAR TAILGATE (LOCK ACTUATOR)	Damaged	395.00 FL	*395.00 FL
12	1		*REAR TAILLAMP LH	Cracked	338.00 FL	*338.00 FL
13	1		*REAR TAILLAMP PANEL LH	Repair	478.80 FL	*- FL
14	1		*REAR END PANEL INNER	Dented	257.60 FL	*257.60 FL
15	1		*REAR END PANEL OUTER	Dented	499.66 FL	*499.66 FL
16	1		*REAR END STEP PANEL	Repeated	175.00 FL	*- FL
17	1		*REAR EXHAUST SILENCER BOX	Repair	931.70 FL	*- FL
18	1		*REAR EXHAUST SILENCER RUBBER MOUNTING	Not Necessary	75.30 FL	*- FL
19	1		*REAR SPARE TYRE BRACKET	Not Necessary	269.00 FL	*- FL
20	1		*REAR SPARE TYRE RETAINER LOCK	Not Necessary	56.00 FL	*- FL
21	1		*REAR FENDER LH	Repair	2,010.50 FL	*- FL
22	1		*REAR FENDER INNER SHIELD LH	Not Necessary	110.00 FL	*- FL
23	1		*REAR WINDSCREEN MOLDING	Necessary	85.00 FL	*85.00 FL
24	1		*REAR WIPER MOTOR	Damaged	485.00 FL	*485.00 FL
25	1		*REAR BUMPER	Deformed	817.80 FL	*696.00 FL
26	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
27	1		*SET REAR CAR PLATE WITH HOLDERS	Not Necessary	70.00 FS	*- FS
28	1		*REAR TAILGATE 70KM/H STICKER	Necessary	70.00 FS	*15.00 FS
29	1		*REAR TAILGATE 8 PAX STICKER	Necessary	70.00 FS	*15.00 FS
30	1		*SET REAR TAILGATE COMPANY FULL SET STICKER	Necessary	150.00 FS	*150.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
32	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
34	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,329.56	6,225.66
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,150.96	589.57
Total Parts (\$\$)	11,178.60	5,636.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	1,300.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	1,300.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	60.00
5	TO CONDUCT WATER SEEPAGE TEST	New	180.00	0.00
6	TO REMOVE REAR BOOT MECHANISM	New	230.00	80.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
8	TO RESPRAY TUFF KOTE	New	280.00	60.00
Gross Labour Cost (\$\$)			4,570.00	2,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >