Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20012169/UTD3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Date of Loss: 03/11/2020 Nature of Claim: TP Claim No: CDMCG20001614

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF4031D

Make & Model: FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT Engine No: 263A50007728734

GLAZE (M)

Reg. Date: 07/10/2016 (Man. Year: 2016) Chassis No: ZFA26300006D40791

 Reg. Date:
 07/10/2016 (Man. Year: 2016)
 Chassis No:
 ZFA263000

 Colour:
 White
 Odometer:
 116529 km

Engine Capacity: 1598 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
Front Left Side: Nexen 6 mm Rear Left Side: Lassa 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Lassa 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,883.10	5,139.17	2,743.93	34.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,010.00	550.00	35.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,443.10	6,149.17	3,293.93	34.88
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	9,443.10	4,900.00	4,543.10	48.11
+ GST 7.00/7.00% (S\$)	661.02	343.00	318.02	48.11
Nett Amount (S\$)	10,104.12	5,243.00	4,861.12	48.11

INSPECTION

Date of Assignment: 06/11/2020

Date Inspected: 06/11/2020 Inspected At: Liu's Brother Auto Workshop (HQ)

1 Kaki Bukit Ave 6 #01-01, Auto

Bay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2020)		
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	e: (Unsubmitted, no print-code for GBF4031D)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Badly Dented	2,342.00 F	*2,342.00 FL
2	1		*FRONT RH DOOR OUTER PROTECTOR	Bent	320.00 F	*268.62 FL
3	1		*FRONT RH DOOR INNER RUBBER	Not Necessary	385.40 F	*-FL
4	1		*FRONT RH DOOR INNER TRIM BOARD	Cut	420.00 F	*420.00 FL
5	1		*FRONT RH DOOR GLASS	Shattered	456.00 F	*456.00 FL
6	1		*FRONT RH DOOR GLASS MOULDING	Scratched	294.00 F	*188.20 FL
7	1		*FRONT RH DOOR VIEW MIRROR	Broken	1,142.80 F	*795.40 FL
8	1		*FRONT RH SIDE MIRROR CONTROL SWITCH	Cracked	268.90 F	*268.90 FL
9	1		*FRONT RH FENDER	Dented/Bent	780.00 F	*699.20 FL
10	1		*FRONT RH FENDER COWLING	Not Necessary	466.00 F	*-FL
11	1		*FRONT RH FENDER COVER BLACK GARNISH	Cracked	640.00 F	*105.20 FL
12	1		*FRONT RH DOOR BLACK STICKER	Necessary	260.00 FS	*120.00 FS
13	1		*FRONT RH DOOR LTA CORPORATE DETAIL STICKER	Necessary	48.00 FS	*30.00 FS
14	1		*SET FRONT RH FENDER COWLING CLIPS	Not Necessary	60.00 FS	*-FS
F=Fra	nchise	part. S=S	pcNett. L=ListItemDisc.			
				Sub Total (S\$)	•	5,693.52
			- List Item Discount on L Items	s 0.00/10.00% (S\$)	0.00	554.35
				Total Parts (S\$)	7,883.10	5,139.17

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	350.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	600.00	550.00
3	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	60.00
4	TO REMOVE,REPLACE AND TRANSFER DOOR PANEL,FITTING AND MECHANISMS	New	80.00	50.00
	Gross Labour Cost (S\$)		1,560.00	1,010.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.