

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20012170/NQF3E2

**Date:** 11/01/2021

### REFERENCE

Insured/Claimant: MOHAMMAD NURRAIHAN BIN RAHMAT

Policy No: 2070032789

Date of Loss: 04/11/2020

Nature of Claim: OD

Claim No: 0963939792SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ8256M**

Make & Model: YAMAHA AEROX GDR155A, 155cc CVT ABS

Engine No: G3J8E0108570

Reg. Date: 23/12/2019 (Man. Year: 2019)

Chassis No: MH3SG4640KJ057437

Colour: Black

Odometer: 16081 km

Engine Capacity: 155 cc

Market Value/New Car Price: S\$12,000.00

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 110/80 R14

Rear Tyre Size: 140/70 R14

Front Left Side: IRC 3 mm

Rear Left Side: IRC 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,360.20	3,737.70	622.50	14.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	520.00	1,260.00	70.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,140.20</b>	<b>4,257.70</b>	<b>1,882.50</b>	<b>30.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>- Excess (S\$)</b>	300.00	300.00	0.00	0.00
<b>(S\$)</b>	5,840.20	3,100.00	2,740.20	46.92
<b>+ GST 7.00/7.00% (S\$)</b>	408.81	217.00	191.81	46.92
<b>Nett Amount (S\$)</b>	<b>6,249.01</b>	<b>3,317.00</b>	<b>2,932.01</b>	<b>46.92</b>

### INSPECTION

Date of Assignment: 06/11/2020

Date Inspected: 09/11/2020

Inspected At:

Bike Production Pte Ltd (HQ)  
610 SERANGOON ROAD  
Singapore 218216

Estimated Period of Repair: 3.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front mudguard rear cover	Missing	75.00 FL	*75.00 FL
2	1		*Front mudguard	Cracked	95.00 FL	*95.00 FL
3	1		*Wheel axle	Bent	60.00 FL	*60.00 FL
4	1		*Brake disk	Serviceable	185.00 FL	*- FL
5	1		*Right fork assy	Scratched	420.00 FL	*420.00 FL
6	1		*Left fork assy	Scratched	420.00 FL	*420.00 FL
7	1		*Steering stem	Bent	220.00 FL	*220.00 FL
8	2		*Steering stem bearings	Necessary	90.00 FL	*90.00 FL
9	1		*Centre cover inner body	Deformed	120.00 FL	*120.00 FL
10	1		*Centre cover lower	Deformed	140.00 FL	*140.00 FL
11	1		*Front cover	Cracked	95.00 FL	*95.00 FL
12	1		*Headlamp lower cover	Missing	75.00 FL	*75.00 FL
13	1		*Left front fairing	Scratched	150.00 FL	*150.00 FL
14	1		*Left front fairing amblems	Scratched	35.00 FL	*35.00 FL
15	1		*Left front fairing inner	Cracked	85.00 FL	*65.00 FL
16	1		*Right front fairing	Missing	150.00 FL	*150.00 FL
17	1		*Right front fairing amblems	Missing	35.00 FL	*35.00 FL
18	1		*Right front fairing inner	Deformed	85.00 FL	*65.00 FL
19	1		*Right floor step	Deformed	105.00 FL	*105.00 FL
20	1		*Left floor step	Scratched	105.00 FL	*105.00 FL
21	1		*Mainstand	Scratched	195.00 FL	*195.00 FL
22	1		*Left engine cover	Scratched	198.00 FL	*198.00 FL
23	1		*Left rear footrest	Scratched	35.00 FL	*35.00 FL
24	1		*Left rear cover	Scratched	145.00 FL	*145.00 FL
25	1		*Left rear cover amblem	Scratched	35.00 FL	*35.00 FL
26	1		*Top cover front	Cracked	95.00 FL	*95.00 FL
27	1		*Top cover front amblem	Necessary	15.00 FL	*15.00 FL
28	1		*Front sport rim	Serviceable	420.00 FS	*- FS
29	1		*Headlamp bracket	Bent	185.00 FL	*185.00 FL
30	1		*Headlamp	Cracked	320.00 FL	*320.00 FL
31	1		*Front right signal	Scratched	95.00 FL	*95.00 FL
32	1		*Front cover amblem	Necessary	25.00 FL	*25.00 FL
33	1		*Left lower cover	Scratched	145.00 FL	*145.00 FL
34	1		*Body right in	Cracked	145.00 FL	*145.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,798.00	4,153.00
- List Item Discount on L Items 10.00/10.00% (S\$)	437.80	415.30
Total Parts (S\$)	4,360.20	3,737.70

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Towing charges	New	100.00	0.00
2	Replace, realign and adjust above damaged parts, check wiring and lighting system	New	700.00	300.00
3	To remove, replace and balance front wheel rim	New	120.00	0.00
4	To knock, straighten chassis & body balancing	New	380.00	0.00
5	To remove/refit, replace (if damage) check and straighten front fork tubes.	New	180.00	120.00
6	Spray painting.	New	300.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,780.00</b>	<b>520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >