

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012174/USD3Q2

Date: 02/12/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00042222000

Claimant Vehicle No : SMC1993H Insured Vehicle No : GY5195Z

Date of Loss: 31/10/2020 Nature of Claim: TP Claim No: SNM20D204181/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC1993H**

Make & Model: HONDA CIVIC, 1.3 IMA CVT (A) Engine No: LDA24010280

Reg. Date: 04/01/2010 (Man. Year: 2008) Chassis No: JHMF36209S202232

Colour: Black Odometer: 274290 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Dunlop 5 mm Rear Left Side: Premio 60 5 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Firenza 5 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 28,413.00         | 11,162.48         | 17,250.52         | 60.71         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 6,800.00          | 3,900.00          | 2,900.00          | 42.65         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>35,213.00</b>  | <b>15,062.48</b>  | <b>20,150.52</b>  | <b>57.22</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>12,000.00</b>  |                   |               |
| <b>(\$\$)</b>                             | 35,213.00         | 12,000.00         | 23,213.00         | 65.92         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 2,464.91          | 840.00            | 1,624.91          | 65.92         |
| <b>Nett Amount (\$\$)</b>                 | <b>37,677.91</b>  | <b>12,840.00</b>  | <b>24,837.91</b>  | <b>65.92</b>  |

### INSPECTION

Date of Assignment: 05/11/2020

Date Inspected: 12/11/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                               |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 01 Dec 2020)                 |
| <b>Parts:</b>        | 143                                                                                                                                                                          | HONDA CIVIC 1.3 IMA CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                             |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMC1993H)                                                                                                                                    |                                                               |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                               |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                               |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                | Condition              | Repairer's | Amount       |
|-----|-----|----------|--------------------------------------------|------------------------|------------|--------------|
| 1   | 1   |          | *REAR BUMPER                               | Distorted              | 845.00 F   | *638.00 FL   |
| 2   | 1   |          | *REAR BUMPER SIDE RETAINERS                | O/s Bent               | 53.00 F    | *26.50 FL    |
| 3   | 1   |          | *SET REAR BUMPER CLIPS                     | Necessary              | 39.00 F    | *39.00 FL    |
| 4   | 1   |          | *BOOTLID                                   | Repair                 | 810.50 F   | *- FL        |
| 5   | 1   |          | *BOOTLID REAR LOGO                         | Necessary              | 38.80 F    | *38.80 FL    |
| 6   | 1   |          | *BOOTLID CIVIC EMBLEM                      | Necessary              | 39.50 F    | *39.50 FL    |
| 7   | 1   |          | *BOOTLID HYBRID EMBLEM                     | Necessary              | 45.00 F    | *45.00 FL    |
| 8   | 1   |          | *BOOTLID REFLECTORS                        | O/s Cracked            | 651.00 F   | *280.20 FL   |
| 9   | 1   |          | *BOOTLID WEATHERSTRIP                      | Not Necessary          | 161.00 F   | *- FL        |
| 10  | 1   |          | *BOOTLID INNER LOCK                        | Not Necessary          | 196.60 F   | *- FL        |
| 11  | 1   |          | *REAR END PANEL                            | Repair                 | 380.80 F   | *- FL        |
| 12  | 1   |          | *REAR END PANEL TOP GARNISH                | Not Necessary          | 166.80 F   | *- FL        |
| 13  | 1   |          | *REAR FENDER O/S                           | Badly Dented           | 991.90 F   | *899.20 FL   |
| 14  | 1   |          | *REAR FENDER INNER TRIM O/S                | Distorted              | 288.80 F   | *266.50 FL   |
| 15  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS O/S      | Necessary              | 39.00 F    | *39.00 FL    |
| 16  | 1   |          | *REAR WINDSCREEN MOULDING                  | Necessary              | 98.10 F    | *98.10 FL    |
| 17  | 1   |          | *BONNET                                    | Buckled                | 788.20 F   | *606.70 FL   |
| 18  | 1   |          | *BONNET INSULATOR                          | Distorted              | 155.50 F   | *155.50 FL   |
| 19  | 1   |          | *SET BONNET INSULATOR CLIPS                | Necessary              | 50.00 F    | *39.00 FL    |
| 20  | 2   |          | *BONNET HINGES                             | Bent                   | 199.00 F   | *199.00 FL   |
| 21  | 1   |          | *BONNET LOCK                               | Twisted                | 162.80 F   | *162.80 FL   |
| 22  | 1   |          | *BONNET LOCK CABLE                         | Jammed                 | 101.00 F   | *101.00 FL   |
| 23  | 1   |          | *FRONT BUMPER                              | Distorted              | 738.00 F   | *738.00 FL   |
| 24  | 1   |          | *FRONT BUMPER CENTRE GRILLE                | Distorted              | 366.50 F   | *212.50 FL   |
| 25  | 2   |          | *FRONT BUMPER SIDE RETAINERS               | Bent                   | 51.00 F    | *51.00 FL    |
| 26  | 1   |          | *SET FRONT BUMPER CLIPS                    | Necessary              | 39.00 F    | *39.00 FL    |
| 27  | 1   |          | *FRONT BUMPER FOG LAMPS                    | N/s Cracked            | 850.00 F   | *385.20 FL   |
| 28  | 1   |          | *FRONT BUMPER LICENCE PLATE GARNISH        | Serviceable            | 66.20 F    | *- FL        |
| 29  | 2   |          | *HEADLAMPS                                 | N/s Broken/O/s Cracked | 3,640.00 F | *1,891.00 FL |
| 30  | 1   |          | *HEADLAMP LOWER BRACKETS                   | N/s Bent               | 91.00 F    | *45.50 FL    |
| 31  | 1   |          | *FRONT FENDERS                             | N/s Buckled/O/s Repair | 1,377.00 F | *450.80 FL   |
| 32  | 2   |          | *FRONT FENDER INNER TOP GARNISHS           | Not Necessary          | 93.60 F    | *- FL        |
| 33  | 2   |          | *FRONT FENDER INNER SHIELDS                | Not Necessary          | 362.00 F   | *- FL        |
| 34  | 1   |          | *FRONT SUPPORT PANEL                       | Bent                   | 655.10 F   | *511.00 FL   |
| 35  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH           | Distorted              | 188.90 F   | *188.90 FL   |
| 36  | 1   |          | *SET FRONT SUPPORT PANEL TOP GARNISH CLIPS | Necessary              | 39.00 F    | *39.00 FL    |
| 37  | 1   |          | *FRONT GRILLE                              | Broken                 | 366.20 F   | *224.60 FL   |
| 38  | 1   |          | *FRONT GRILLE H LOGO                       | Missing                | 38.90 F    | *38.90 FL    |
| 39  | 1   |          | *FRONT GRILLE CHROME                       | Broken                 | 299.90 F   | *111.90 FL   |
| 40  | 1   |          | *FRONT WIPER GARNISH                       | Not Necessary          | 355.20 F   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's | Amount       |
|-----|-----|----------|--------------------------------------|---------------|------------|--------------|
| 41  | 1   |          | *AIR CON CONDENSER                   | Distorted     | 1,050.00 F | *823.00 FL   |
| 42  | 1   |          | *AIR CON DISCHARGE HOSE              | Serviceable   | 281.90 F   | *- FL        |
| 43  | 1   |          | *AIR CON SUCTION HOSE                | Serviceable   | 311.10 F   | *- FL        |
| 44  | 1   |          | *AIR CON LIQUID PIPE                 | Bent          | 199.80 F   | *166.50 FL   |
| 45  | 1   |          | *AIR CON FAN COWLING                 | Cracked       | 155.80 F   | *101.50 FL   |
| 46  | 1   |          | *AIR CON FAN MOTOR                   | Jammed        | 450.50 F   | *450.50 FL   |
| 47  | 1   |          | *AIR CON FAN BLADE                   | Bent          | 122.00 F   | *122.00 FL   |
| 48  | 1   |          | *RADIATOR                            | Distorted     | 1,688.20 F | *1,544.80 FL |
| 49  | 1   |          | *RADIATOR FAN COWLING                | Cracked       | 145.90 F   | *101.50 FL   |
| 50  | 1   |          | *RADIATOR FAN MOTOR                  | Jammed        | 450.00 F   | *450.00 FL   |
| 51  | 1   |          | *RADIATOR FAN BLADE                  | Bent          | 122.00 F   | *122.00 FL   |
| 52  | 1   |          | *RADIATOR TOP HOSE                   | Serviceable   | 85.00 F    | *- FL        |
| 53  | 2   |          | *RADIATOR TOP BRACKETS               | Bent          | 30.00 F    | *30.00 FL    |
| 54  | 1   |          | *HORN UNIT                           | Not Necessary | 86.90 F    | *- FL        |
| 55  | 1   |          | *WASHER TANK                         | Not Necessary | 145.70 F   | *- FL        |
| 56  | 1   |          | *ALTERNATOR                          | Not Necessary | 1,668.20 F | *- FL        |
| 57  | 1   |          | *ABS PUMP                            | Not Necessary | 2,350.90 F | *- FL        |
| 58  | 1   |          | *RADIATOR SPARE TANK                 | Deformed      | 142.30 F   | *86.50 FL    |
| 59  | 1   |          | *HEADLAMP TOP SIDE PANEL N/S         | Bent          | 166.40 F   | *166.40 FL   |
| 60  | 1   |          | *AIR DUCT                            | Distorted     | 188.60 F   | *145.20 FL   |
| 61  | 1   |          | *AIR DUCT FILTER ASSY                | Cracked       | 658.90 F   | *620.20 FL   |
| 62  | 1   |          | *AIR INTAKE MANIFOLD                 | Serviceable   | 1,288.20 F | *- FL        |
| 63  | 1   |          | *FRT BUMPER REINFORCEMENT            | Bent          | 246.90 F   | *246.90 FL   |
| 64  | 1   |          | *FRONT LICENCE PLATE                 | Broken        | 50.00 FS   | *40.00 FS    |
| 65  | 1   |          | *BOT RADIATOR COOLANT                | Necessary     | 50.00 FS   | *30.00 FS    |
| 66  | 1   |          | *BOL AIR CON OIL                     | Necessary     | 50.00 FS   | *30.00 FS    |
| 67  | 1   |          | *BATTERY                             | Serviceable   | 220.00 FS  | *- FS        |
| 68  | 1   |          | *REAR WINDSCREEN SEALANT             | Necessary     | 50.00 FS   | *40.00 FS    |
| 69  | 1   |          | *SET FRONT FENDER INNER SHIELD CLIPS | Not Necessary | 39.00 F    | *- FL        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (S\$) 28,413.00 13,918.10**  
**- List Item Discount on L Items 0.00/20.00% (S\$) 0.00 2,755.62**

**Total Parts (S\$) 28,413.00 11,162.48**

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                           |          |                 |                 |
| 1                               | TO CHECK WIRING                           | New      | 50.00           | 30.00           |
| 2                               | TO DISMANTLE & REFIX REAR REVERSE SENSOR  | New      | 80.00           | 50.00           |
| 3                               | TO DISMANTLE & FIX CUSHION UPHOLSTERY     | New      | 120.00          | 80.00           |
| 4                               | TO TRANSFER BOOTLID MECHANISM             | New      | 100.00          | 0.00            |
| 5                               | TO DISMANTLE & REFIX REAR WINDSCREEN      | New      | 150.00          | 120.00          |
| 6                               | TO DISMANTLE & REFIX FUEL TANK            | New      | 100.00          | 0.00            |
| 7                               | TO SPRAY RUST PROOFING                    | New      | 180.00          | 120.00          |
| 8                               | TO REFILL AIR CON GAS                     | New      | 120.00          | 100.00          |
| 9                               | TO RESET & REPROGRAMME FAULT CODE         | New      | 100.00          | 0.00            |
| 10                              | LABOUR FOR PANEL BEATING & REPLACED PARTS | New      | 3,000.00        | 1,600.00        |
| 11                              | TO PUTTY & SPRAY PAINTING                 | New      | 2,800.00        | 1,800.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                           |          | <b>6,800.00</b> | <b>3,900.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >