

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19021540/T1QF3E2**Date:** 21/12/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29082547

Claimant Vehicle No : YQ866H**Insured Vehicle No :** SJF1187M

Date of Loss: 18/11/2019

Nature of Claim: TP Claim No: 612055

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YQ866H**

Make & Model: MERCEDES-BENZ SPRINTER 516CDI, 2.1 D 4325 EL AT TURBO (A)

Engine No: 65195534790590

Reg. Date: 10/05/2019 (Man. Year: 2018)

Chassis No: WDB9062532N773768

Colour: White

Odometer: 19079 km

Engine Capacity: 2143 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/75 R16

Rear Tyre Size: 205/75 R16 (D)

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7/7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7/7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/12/2019

Date Inspected: 06/11/2020 Inspected At:

Woon Meng Motor Pte Ltd (Bukit Batok)
50 Bukit Batok Street 23,, #01-06 Midview Building
Singapore 659578

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF
\$600.00-\$1,200.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Dec 2021)	
Parts:	N/A	MERCEDES-BENZ SPRINTER 516CDI 2.1 D 4325 EL AT TURBO (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for YQ866H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >