

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20012181/ABS3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0000907_02
Claimant Vehicle No :	GBE8677U	Insured Vehicle No :	PC8778G
Date of Loss:	05/11/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0002308

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE8677U		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30010337N
Reg. Date:	08/04/2016 (Man. Year: 2016)	Chassis No:	JN1SC2F24Z0858421
Colour:	Silver	Odometer:	74260 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/75 R15C	Rear Tyre Size:	155 R13C
Front Left Side:	Kenda 6 mm	Rear Left Side:	APLUS 6 mm
Front Right Side:	Kenda 6 mm	Rear Right Side:	APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,036.40	2,360.00	5,676.40	70.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	780.00	750.00	49.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,566.40	3,140.00	6,426.40	67.18
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	9,566.40	2,500.00	7,066.40	73.87
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,907.45		
Global Sum Settlement (S\$)		2,900.00		

INSPECTION

Date of Assignment:	06/11/2020		
Date Inspected:	06/11/2020	Inspected At:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1 Singapore 408714
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jan 2021)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE8677U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID ALUMINUM	Bent	3,850.00 FS	*200.00 FS
2	1		*REAR BOOT LID 70KM/H LOGO	Not Necessary	35.00 F	*- FL
3	1		*REAR BOOT LID 6 PAX LOGO	Not Necessary	20.00 F	*- FL
4	2		*REAR BOOT LID TOP SIDE LOCK	Not Necessary	366.40 F	*- FL
5	1		*LH SIDE PANEL	Dented	2,200.00 F	*1,890.00 FL
6	4		*REAR SIDE STOPPER RUBBER	Not Necessary	72.40 F	*- FL
7	2		*LH WHEEL ARCH	Dented	310.00 F	*310.00 FL
8	1		*LH SIDE PANEL STICKER	Necessary	250.00 FS	*180.00 FS
9	1		*REAR BOOT LID LOGO	Not Necessary	350.00 F	*- FL
10	1		*TAIL LAMP BRACKET	Not Necessary	58.20 F	*- FL
11	2		*REAR EXHAUST MOUNTING	Not Necessary	74.40 F	*- FL
12	1		*LH SIDE PANEL TOP HANDLE	Not Necessary	450.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,036.40	2,580.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	220.00
Total Parts (\$\$)	8,036.40	2,360.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX LH SIDE PANEL ALUMINIUM BAR	New	280.00	150.00
2	TO CHECK WIRING SYSTEM	New	50.00	30.00
3	PANEL BEATING	New	600.00	300.00
4	SPRAY PAINTING	New	600.00	300.00
Gross Labour Cost (\$\$)			1,530.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >