



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 2389D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT MUDGUARD	NOT NECESSARY	75.00	-
2	FRONT WHEEL AXLE	NOT NECESSARY	60.00	-
2	FRONT FORK ASSY LH & RH @\$240.00	NOT NECESSARY	480.00	-
1	STEM STEERING	NOT NECESSARY	165.00	-
1	HANDLEBAR	NOT NECESSARY	80.00	-
1	CLUTCH LEVER	NOT NECESSARY	40.00	-
1	BRAKE LEVER	CUT	40.00	40.00
2	BALANCER @\$25.00	N/S NOT NECESSARY / O/S CUT	50.00	25.00
2	SIDE MIRROR @\$30.00	NOT NECESSARY	60.00	-
1	FRONT HEADLIGHT COVER	NOT NECESSARY	60.00	-
1	REAR HEADLIGHT COVER	NOT NECESSARY	60.00	-
1	HEADLIGHT ASSY	NOT NECESSARY	160.00	-
1	FRONT MASK	CUT	90.00	90.00
1	FRONT MASK COVERING	CUT	120.00	120.00
1	PILOT LIGHT	CUT	250.00	250.00
1	BELLY SHIELD COVERING	NOT NECESSARY	90.00	-
1	FRONT SIDE FAIRING LH	NOT NECESSARY	95.00	-
1	FRONT SIDE FAIRING RH	CRACKED	95.00	95.00
1	REAR SIDE FAIRING LH	NOT NECESSARY	95.00	-
1	REAR SIDE FAIRING RH	CRACKED	95.00	95.00
1	CENTRE COVERING	NOT NECESSARY	120.00	-
1	FRONT FOOTREST BAR	DENTED	75.00	75.00
1	FRONT FOOTREST RUBBER	DENTED	45.00	45.00
1	GEAR PEDAL	NOT NECESSARY	50.00	-
1	REAR FOOTREST BAR LH	BENT	75.00	75.00
1	GEAR PEDAL RUBBER	NOT NECESSARY	20.00	-
	LESS 10% DISCOUNT		-264.50	-91.00
			2,380.50	819.00

Report Ref No. CS/GAI20012186/T1vd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	NO. PLATE (FRONT) (SN)	NOT NECESSARY	25.00	-
1	NO. PLATE (REAR) (SN)	BENT	25.00	25.00
1	SET CONE BEARING (SN)	NOT NECESSARY	120.00	-
1	IU UNIT (SN)	NOT NECESSARY	160.00	-
1	IU BRACKET (SN)	NOT NECESSARY	40.00	-
1	SET REAR TOP BOX RACK (SN)	BENT	180.00	150.00
1	REAR TOP BOX BASE (SN)	DISTORTED	50.00	50.00
1	REAR TOP BOX (SN)	CUT	300.00	250.00
1	FRONT CENTRE BASKET (SN)	NOT NECESSARY	150.00	-
1	RADIATOR GUARD (SN)	NOT NECESSARY	120.00	-
1	SET STICKER (SN)	NECESSARY	180.00	120.00
			1,350.00	595.00
	<b><u>LABOUR</u></b>			
	TOWING.		120.00	80.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO REALIGN BODY FRAME.	NOT NECESSARY	350.00	-
	TO R&R FRONT SUSPENSION, HANDLE BAR, HEADLAMP, SIDE FAIRING, AND ATTACHEMENTS.		400.00	200.00
	TO RESPRAY ON FRONT FENDER, HEADLAMP CROWING, BOTH SIDE FAIRING AND ACCIDENT AFFECTED AREA.		500.00	200.00
			1,420.00	510.00
	<b>GRAND TOTAL</b>		<b>5,150.50</b>	<b>1,924.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (UN-CONFIRMED)</b>			<b>1,500.00</b>

Report Ref No. CS/GAI20012186/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.