

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20012188/T1YD3E2

**Date:** 24/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900023510
<b>Claimant Vehicle No :</b> FBM8257G	<b>Insured Vehicle No :</b>	SBB98J
Date of Loss: 30/10/2020	Nature of Claim: TP	Claim No: 3895384629SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM8257G	Engine No:	WH161FMK17K01333
Make & Model:	HONDA CB190X, 184cc	Chassis No:	LWBPCL1A7H1003360
Reg. Date:	21/04/2018 (Man. Year: 2017)	Odometer:	0 km
Colour:	White		
Engine Capacity:	184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	CST 5 mm	Rear Left Side:	CST 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	06/11/2020	
Date Inspected:	06/11/2020 Inspected At:	M/s Infinity Motor Pte Ltd (HQ) 1 SOON LEE STREET, #01-37 PIONEER CENTRE Singapore 627605
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK ASSY	* Check	0.00 F	*- F
3	1		*FRONT LH SIGNAL LAMP	Cut	0.00 F	*- F
4	1		*HANDLE BAR	* Check	0.00 F	*- F
5	1		*SIDE FAIRING LH	Cut	0.00 F	*- F
6	1		*FRONT FOOT REST	Cut	0.00 F	*- F
7	1		*REAR FENDER WHEEL GUARD	Deformed	0.00 F	*- F
8	1		*SWING ARM	* Check	0.00 F	*- F
9	1		*REAR LH SIGNAL LAMP	Distorted	0.00 F	*- F
10	1		*REAR RH SIGNAL LAMP	Distorted	0.00 F	*- F
11	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
12	1		*REAR BOX	Cut	0.00 F	*- F
13	1		*REAR BOX BRACKET	* Check	0.00 F	*- F
14	1		*STICKER	Necessary	0.00 F	*- F
15	1		*HELMET	Cracked	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**