

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20012194/ARA3Q2
Date: 05/05/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100462886
Claimant Vehicle No :	GBF4849L	Insured Vehicle No :	GBE9421J
Date of Loss:	28/10/2020	Nature of Claim:	TP
		Claim No:	3780721457SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4849L	Engine No:	1KD2579459
Make & Model:	TOYOTA HIACE, 3.0 D DX (M)	Chassis No:	KDH2010186698
Reg. Date:	03/11/2016 (Man. Year: 2015)	Odometer:	52809 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Longway 6 mm	Rear Left Side:	Longway 6 mm
Front Right Side:	Longway 6 mm	Rear Right Side:	Longway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,820.25	3,361.51	3,458.74	50.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	1,650.00	520.00	23.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,990.25	5,011.51	3,978.74	44.26
Approved Total (Overridden) (S\$)		4,000.00		

Nett Amount (S\$)	8,990.25	4,000.00	4,990.25	55.51
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,567.45		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment: 05/11/2020

Date Inspected: 05/11/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Sin Fatt Diesel Motor (HQ)
BLK 3020A #01-33 UBI ROAD 1
Singapore 408714**Adjuster:** ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,850.00 F	*1,718.00 FL
2	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	128.10 F	*128.10 FL
3	1		*REAR BOOT LID 70KM LOGO	Necessary	30.00 FS	*10.00 FS
4	1		*REAR BOOT LID EMBLE LOGO	Necessary	66.10 F	*66.10 FL
5	1		*BOOT LID 8 PAX LOGO	Necessary	25.00 FS	*10.00 FS
6	1		*REAR BOOT LID INNER LOCK	Damaged	388.00 F	*275.00 FL
7	1		*REAR BOOT LID CENTRE MOULDING	Not Necessary	209.10 F	*- FL
8	1		*REAR BOOT LID INNER RUBBER	Cut	215.00 F	*215.00 FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	166.40 F	*- FL
10	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
11	1		*REAR STEP PANEL	Bent	158.00 F	*158.00 FL
12	1		*BOOT LID BODY STICKER	Necessary	450.00 FS	*250.00 FS
13	2		*REAR TAIL LAMP	Not Necessary	598.20 F	*- FL
14	2		*REAR TAIL LAMP LOWER SIDE BRACKET	Repair	224.40 F	*- FL
15	1		*REAR BUMPER	Deformed	520.00 F	*520.00 FL
16	4		*REAR BUMPER REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
17	2		*REAR BUMPER SIDE BRACKET	Necessary	242.50 F	*85.00 FL
18	6		*REAR BUMPER CLIPS	Necessary	77.40 F	*30.00 FL
19	4		*REAR BUMPER BRACKET LH/RH	Bent	332.80 F	*80.00 FL
20	1		*REAR END PANEL	Dented	580.15 F	*580.15 FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	209.10 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,820.25	4,325.35
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	963.84
Total Parts (\$)	6,820.25	3,361.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
2	GUM	New	50.00	50.00
3	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
4	TO REMOVE & REFIX REAR CUSHION	New	120.00	40.00
5	TO CHECK WIRING SYSTEM	New	60.00	30.00
6	TUFF KOTE	New	120.00	60.00
7	PANEL BEATING	New	800.00	700.00
8	SPRAY PAINTING	New	800.00	600.00
			Gross Labour Cost (S\$)	2,170.00
				1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >