

SIN FATT DIESEL MOTOR

Block 3020A Ubi Road 1 # 01-33 Singapore 408714
 HP: 92712214
 Business Reg. No : 377435/00K

LASER PACKAGING MACHINE MFG PTE LTD
 BLOCK 3020A UBI ROAD 1
 # 01-33
 Singapore 408714

TP ALG.
 Xiao Tong

06th November 2020

KDH 2010186698

Accident date: 28th OCTOBER 2020
 Estimated repair cost for vehicle no: GBF4849L TOYOTA HIACE 3.0 (2016)

S/n	Qty	Items	U/price	Amount
				\$1,850.00 1718
1	1	Rear Boot Lid <i>Dented</i>		\$128.10
2	1	Rear boot lid windscreen seal <i>new</i>	3855.35	\$30.00 10(SN)
3	1	Rear boot lid 70 KM logo <i>new</i>		\$66.10 ✓
4	1	Rear boot lid emble logo ✓	2891.51	\$25.00 10(SN)
5	1	boot lid 8 pax logo <i>new</i>		\$388.00 275
6	1	Rear boot lid inner lock <i>Dead</i>	8N: 470	\$209.10 X
7	1	Rear boot lid centre moulding <i>new</i>		\$215.00 ✓
8	1	Rear boot lid inner rubber <i>cut</i>		\$166.40 X
9	2	Rear boot lid number plate lamp <i>new</i>	\$83.20	\$50.00 X
10	1	Rear boot lid number plate <i>new</i>		\$158.00 ✓
11	1	rear step panel <i>Bent</i>		\$450.00 250(SN)
12	1	boot lid body <i>Sticker</i> <i>new</i>		\$598.20 X
13	2	Rear tail lamp <i>new</i>	\$299.10	\$224.40 X
14	2	Rear tail lamp lower side bracket <i>Paint</i>	\$112.20	\$520.00 ✓
15	1	Rear bumper <i>Deformed</i>		\$300.00 200(SN)
16	4	Rear bumper reverse sensor <i>Dead</i>		\$242.50 85
17	2	Rear bumper side bracket <i>new</i>	\$121.25	\$77.40 30
18	6	Rear bumper clips <i>new</i>	\$12.90	\$332.80 80
19	4	rear bumper bracket LH / RH <i>Bent</i>	\$83.20	\$580.15 ✓
20	1	Rear end panel <i>Dented</i>		\$209.10 X
22	1	Rear End Panel Top Garnish <i>new</i>		

Subtotal :- \$6,820.25

Labour charges

To remove & re-fix rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

To remove & re-fix reverse sensor

1650

~~\$100.00~~ 50

To remove & re-fix rear cushion

~~\$120.00~~ 40

To Check Wiring System

Total: 5011.51

~~\$60.00~~ 30

Tuff kote

L/S: 41K

~~\$120.00~~ 60

Panel beating

068up

~~\$800.00~~ 700

Spray painting

~~\$800.00~~ 600

Subtotal :- \$2,170.00

Total :- \$8,990.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: