

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 7088R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BROKEN	1,138.60	869.80
2	REAR BUMPER SIDE RETAINER @\$187.20(CONSISTENT)	NECESSARY	374.40	258.40
1	REAR BUMPER REFLECTOR (CONSISTENT)	BROKEN	181.60	65.90
1	REAR BUMPER TOW CAP (CONSISTENT)	NOT DAMAGED	61.20	-
2	REAR BUMPER REVERSE SENSOR @\$380.00 (CONSISTENT)	NOT DAMAGED	760.00	-
1	TAILLAMP LOWER GARNISH RH (CONSISTENT)	DENTED	357.70	357.70
1	TAILLAMP LOWER GARNISH RETAINER RH (CONSISTENT)	BROKEN	172.25	172.25
1	SLIDING DOOR RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,692.00	-
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,583.60	-
1	REAR FENDER INNER INNER TRIM BOARD RH (CONSISTENT)	NOT DAMAGED	982.60	-
1	REAR FENDER INNER COWLING RH (CONSISTENT)	NO SUCH PARTS	186.30	-
1	REAR SIDE GLASS MOULDING RH (CONSISTENT)	NOT NECESSARY	298.30	-
1	REAR AIR VENTS RH (CONSISTENT)	NOT DAMAGED	89.50	-
1	REAR KNUCKLE ARM RH (CONSISTENT)	NOT DAMAGED	428.00	-
1	REAR KNUCKLE ARM BEARING RH (CONSISTENT)	JAMMED	410.60	300.00
1	REAR SHOCK ABSORBER RH (CONSISTENT)	NOT DAMAGED	287.60	-
1	REAR LOWER ARM RH (CONSISTENT)	NOT DAMAGED	368.00	-
1	REAR UPPER ARM RH (CONSISTENT)	NOT DAMAGED	298.65	-
1	REAR A/C COOLING COIL ASSY (CONSISTENT)	BROKEN	1,405.30	1,405.30
	LESS 25% DISCOUNT		-3,019.05	-857.34
			9,057.15	2,572.01
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	30.00
4	REAR BUMPER REVERSE SENSOR SEAL @\$60.00 (SN) (CONSISTENT)	NECESSARY	240.00	240.00
1	TAILLAMP LOWER GARNISH CLIPS (SN) (CONSISTENT)	NO SUCH PARTS	50.00	-
1	SLIDING DOOR SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-

Report Ref No. CC4/ASM20012197/Bba3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR FENDER SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR FENDER INNER INNER TRIM BOARD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR SIDE GLASS SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR SIDE GLASS INNER SEAL (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR SIDE GLASS PRIMER & CLEANER (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	ALLOY RIM (SN) (CONSISTENT)	CUT	980.00	200.00
1	TYRE (SN) (CONSISTENT)	NOT DAMAGED	480.00	-
1	A/C FLUID (SN) (CONSISTENT)	NECESSARY	80.00	80.00
			2,500.00	550.00
	<u>LABOUR</u>			
	R&R REVERSE SENSOR .		100.00	60.00
	R&R REAR SIDE GLASS .	NOT NECESSARY	250.00	-
	R&R REAR UNDER CARRIAGE.		150.00	80.00
	R&R REAR TYRE AND BALANCING .		80.00	40.00
	WHEEL ALIGNMENT .		120.00	60.00
	R&R REAR SEAT .		150.00	70.00
	UPHOLSTERY.	NOT NECESSARY	300.00	-
	DIAGNOSTIC RESET FAULT CODE.	NOT NECESSARY	300.00	-
	CONDUCT WATER LEAK TEST.	NOT NECESSARY	180.00	-
	PANEL BEAT.INCLUSIVE OF THE REPAIR OF SLIDING DOOR RH AND REAR FENDER RH .		1,400.00	1,000.00
	CHECK WIRING .		100.00	50.00
	RUST PROOFING .	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,400.00	1,000.00
			4,730.00	2,360.00
	GRAND TOTAL		16,287.15	5,482.01



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		4,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20012197/Bba3q2

**LIM TEOW GUAN** 

**Automotive Assessor** 

mont

**HO LEONG CHUAN** 

**Automotive Assessor**