

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012198/GTD3 E2

Date: 02/06/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001379622

Claimant Vehicle No : GBB2451J

Insured Vehicle No : WC6103J

Date of Loss: 03/11/2020

Nature of Claim: TP

Claim No: 249406

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB2451J**

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD1875499

Reg. Date: 20/10/2008 (Man. Year: 2008)

Chassis No: JTFAT35Y40K200144

Colour: Yellow

Odometer: 266992 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R12

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,362.20	3,336.87	2,025.33	37.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,280.00	1,160.00	47.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,802.20	4,616.87	3,185.33	40.83
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	7,802.20	3,400.00	4,402.20	56.42
+ GST 7.00/7.00% (S\$)	546.15	238.00	308.15	56.42
Nett Amount (S\$)	8,348.35	3,638.00	4,710.35	56.42

INSPECTION

Date of Assignment: 09/11/2020

Date Inspected: 08/11/2020 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jun 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB2451J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP L/R	Cracked	121.40 FL	*97.00 FL
2	1		*REAR NUMBER PLATE PANEL	Bent	228.60 FL	*119.50 FL
3	1		*REAR RUBBER STOPPER BRACKET R/L	N/S Bent / O/S Not Necessary	197.20 FL	*98.60 FL
4	1		*REAR RUBBER STOPPER R/L	N/S Cut / O/S Not Necessary	86.20 FL	*43.10 FL
5	1		*REAR TAILGATE	Buckled	1,116.70 FL	*1,116.70 FL
6	1		*REAR TAILGATE FLIP LOCK HANDLE L/R	N/S Bent / O/S Not Necessary	231.80 FL	*115.90 FL
7	4		*REAR TAILGATE HINGES	Repair	416.00 FL	*- FL
8	1		*REAR TAILGATE LOWER PANEL	Buckled	585.50 FL	*585.50 FL
9	2		*REAR TAILLAMP BRACKET R/L	Bent	123.60 FL	*123.60 FL
10	2		*REAR TAILLAMP R/L	Cracked	502.60 FL	*502.60 FL
11	1		*REAR FLOOR ALUMINIUM CHECKER BOARD	Bent	1,000.00 FS	*550.00 FS
12	1		*REAR FLOOR ALUMINIUM CEHCKER BOARD REPAIR KIT	Not Necessary	100.00 FS	*- FS
13	1		*REAR HOLDER BRACKET	Bent	500.00 FS	*150.00 FS
14	1		*REAR NUMBER PLATE	Bent	25.00 FS	*15.00 FS
15	1		*REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
16	1		*REAR STEP BRACKET	Bent	450.00 FS	*250.00 FS
17	1		*REAR TAILGATE 6PAX STICKER	Necessary	25.00 FS	*10.00 FS
18	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*10.00 FS
19	1		*REAR TAILGATE ART WORK STICKER	Necessary	280.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,264.60	4,037.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	902.40	700.63
Total Parts (\$\$)	5,362.20	3,336.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,100.00	600.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	50.00
Gross Labour Cost (\$)			2,440.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >