

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20012201/R1BA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SMQ4938A	Insured Vehicle No :	GBH213L
Date of Loss:	04/11/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002322

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4938A		
Make & Model:	MAZDA CX-5 5-DOOR WAGON, 2.0 L SP.6EAT (A)	Engine No:	PE30773245
Reg. Date:	19/06/2015 (Man. Year: 2015)	Chassis No:	JM6KE1072G0319831
Colour:	Black	Odometer:	97450 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,047.40	849.00	198.40	18.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,635.00	3,060.00	1,575.00	33.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,682.40	3,909.00	1,773.40	31.21
+ GST 7.00/7.00% (\$\$)	397.77	273.63	124.14	31.21
Nett Amount (\$\$)	6,080.17	4,182.63	1,897.54	31.21
+ Loss of Use (5.0 x S\$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,690.08		

INSPECTION

Date of Assignment: 06/11/2020

Date Inspected: 09/11/2020 Inspected At:

Trans Eurokars Pte Ltd - Tanjong
Penjuru (HQ)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Apr 2021)
Parts:	M1-SUV	MAZDA CX-5 5-DOOR WAGON 2.0 L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ4938A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RHS	Buckled	512.30 F	*512.30 F
2	1		*STAY RHS FRONT FENDER	Necessary	60.00 F	*60.00 F
3	1		*MUDGUARD RHS	Serviceable	128.40 F	*- F
4	1		*FASTENER ,MUDGUARD	Necessary	60.00 F	*60.00 F
5	1		*GARNISH ,FRONT FENDER	Deformed	186.70 F	*186.70 F
6	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **1,047.40** **849.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT FENDER RH REPAIR FRONT DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	1,650.00	630.00
2	TO RESPRAY FRONT FENDER RH AND FRONT DOOR RH	New	1,575.00	1,320.00
3	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
5	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOUK)	New	250.00	150.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	250.00
Gross Labour Cost (S\$)			4,635.00	3,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >