Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012202/KGA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900258808

Claimant
Vehicle No: SJP5382L Insured Vehicle No: SMR3218X

Date of Loss: 01/11/2020 Nature of Claim: TP Claim No: 6509210256SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP5382L

 Make & Model:
 TOYOTA ALLION, 1.5 (A)
 Engine No:
 1NZD312254

 Reg. Date:
 27/03/2009 (Man. Year: 2008)
 Chassis No:
 NZT2603039118

 Colour:
 Metallic Dark Blue
 Odometer:
 230183 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm
Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,667.70	1,550.25	117.45	7.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	400.00	550.00	57.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,617.70	1,950.25	667.45	25.50
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	2,617.70	1,550.00	1,067.70	40.79
+ GST 7.00/7.00% (S\$)	183.24	108.50	74.74	40.79
Nett Amount (S\$)	2,800.94	1,658.50	1,142.44	40.79
+ Loss of Use (3.0 x S\$(60.00/day) (S\$)	180.00		
+ Doc/S	earch Fee (S\$)	2.00		
Ne	tt Liability (S\$)	1,840.50		

INSPECTION

Date of Assignment: 06/11/2020

Date Inspected: 10/11/2020 Inspected At: City Auto Pte Ltd

Blk 13, Sin Ming Industrial Estate

Sector B, #01-47/49 Singapore 575657

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount			
1	1		*TAIL LAMP -RH	Cut	384.10 FL	*384.10 FL			
2	1		*REAR BUMPER	Buckled	1,682.90 FL	*1,682.90 FL			
3	1		*REAR BUMPER RETAINER RH	Serviceable	96.80 FL	*- FL			
4	1		*REAR BUMPER REFLECTOR RH	Serviceable	59.80 FL	*- FL			
F=Franchise part. L=ListItemDisc.									
				Sub Total (S\$)	2,223.60	2,067.00			
- List Item Discount on L Items 25.00/25.00% (S\$)				555.90	516.75				
				Total Parts (S\$)_	1,667.70	1,550.25			
Report was unsubmitted during this print-out.									

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Lab	our Items				
1	TO KNOCK JACKOUT DAMAGE PARTS, PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	400.00	200.00	
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	550.00	200.00	
	Gross Labour Cost (S\$)		950.00	400.00	
Report was unsubmitted during this print-out					

< END OF ESTIMATES >